



PEUGEOT



RK56UCG

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Black
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G





## MOT history

MOT expiry date	2021-06-02
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	35
Total items failed	5

MOT #15	2020-06-03 14:17
MOT test number	154816987902
Result	✓ Passed
Next expiry date	2021-06-02
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #14	2020-06-03 09:16
MOT test number	983130047119
Result	✗ Failed
Fail	Offside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #13**

2019-04-23 08:42

**MOT test number**

455839441337

**Result**

✓ Passed

- Advice** Coolant leak
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear exhaust box poor condition
- Advice** Front Sub-frame damaged but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2018-05-09 09:10

**MOT test number**

959071400739

**Result**

✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Fuel tank support strap corroded/weak
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
- Advice** Front Sub-frame damaged but not seriously weakened (2.4.G.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear tyre cracked/perished on outer wall
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #11**

2017-05-09 10:54

**MOT test number**

418777350695

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit worn on inside edge (4.1.E.1)**Advice** Offside Rear tyre cracked on wall**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #10**

2016-05-13 11:36

**MOT test number**

291224525323

**Result**

✓ Passed

**Advice** Rear tyres slightly perished on sidewalls**Advice** Rear silencer corroded**Advice** Power steering switch weeping**MOT #9**

2016-05-13 08:33

**MOT test number**

767974573623

**Result**

✗ Failed

**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** N/s wiper blade split on ends**Advice** Rear tyres slightly perished on sidewalls**Advice** Rear silencer corroded**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Power steering switch weeping

**MOT #8** 2015-05-19 17:12**MOT test number** 179059435142**Result** ✓ Passed**MOT #7** 2014-06-19 10:10**MOT test number** 599090674128**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-06-17 10:09**MOT test number** 125978463177**Result** ✓ Passed**MOT #5** 2012-07-05 10:24**MOT test number** 779957582173**Result** ✓ Passed**MOT #4** 2011-07-05 13:56**MOT test number** 267816781121**Result** ✓ Passed**MOT #3** 2011-07-05 13:56**MOT test number** 908876281126**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)



MOT #2	2010-07-05 09:25
MOT test number	400446680110
Result	✓ Passed

  

MOT #1	2009-07-07 10:38
MOT test number	501658989175
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-09-04
Last registration	2020-06-03
Complete history	<a href="#">See info</a>



Registration #1	2006-09-04	10 mi
Registration #2	2009-07-07	9.390 mi
Registration #3	2010-07-05	12.090 mi
Registration #4	2011-07-05	16.754 mi
Registration #5	2012-07-05	23.152 mi
Registration #6	2013-06-17	30.728 mi
Registration #7	2014-06-19	36.819 mi
Registration #8	2015-05-19	39.435 mi
Registration #9	2016-05-19	42.051 mi
Registration #10	2017-05-19	44.667 mi
Registration #11	2018-05-19	47.283 mi
Registration #12	2019-05-19	49.899 mi
Registration #13	2020-05-19	52.515 mi
Registration #14	2021-05-19	55.131 mi
Registration #15	2022-05-19	57.747 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FST65298536