



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D5 SE LUX NAV AWD
Colour	Grey
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	217 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 2

Date	2021-09-13
Pictures	23
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-09-09
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-24
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	6

MOT #8	2023-10-17 10:09
MOT test number	103493536837
Result	✓ Passed
Next expiry date	2024-10-24
Advice	Rear Brake pad(s) wearing thin pads 85% worn (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside worn/lipped (1.1.14 (a) (ii))

MOT #7	2023-10-17 08:58
MOT test number	665244024371
Result	✗ Failed
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on inner edge (5.2.3 (d) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside worn/lipped (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin pads 85% worn (1.1.13 (a) (ii))
Fail	Offside Front Tyre has ply or cords exposed cords exposed on inner edge (5.2.3 (d) (ii))

MOT #6	2022-10-20 10:28
MOT test number	845412360834
Result	✓ Passed

**MOT #5** 2021-10-25 13:26**MOT test number** 248287546226**Result** ✓ Passed**MOT #4** 2020-08-06 09:35**MOT test number** 884897988579**Result** ✓ Passed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2019-08-14 15:27**MOT test number** 660146387056**Result** ✓ Passed**MOT #2** 2018-08-16 08:38**MOT test number** 924741006429**Result** ✓ Passed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))



MOT #1	2018-08-15 12:45
MOT test number	591437760590
Result	✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (i))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
Fail	Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (i))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-12
Last registration	2023-10-17
Complete history	See info



Registration #1	2015-09-12	22 mi
Registration #2	2018-08-15	25.266 mi
Registration #3	2018-08-16	25.266 mi
Registration #4	2019-08-14	29.159 mi
Registration #5	2020-08-06	35.396 mi
Registration #6	2021-08-06	35.396 mi
Registration #7	2021-08-06	35.396 mi
Registration #8	2021-08-06	35.396 mi
Registration #9	2021-08-06	35.396 mi
Registration #10	2021-08-06	35.396 mi
Registration #11	2021-08-06	35.396 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1865 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1614888