



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO XE
Colour	Black
Year of manufacture	2008
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.2 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.8 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-22
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-25
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	38
Total items failed	20

MOT #17	2023-08-18 14:15
MOT test number	534681931170
Result	✓ Passed
Next expiry date	2024-08-25
Advice	Items removed from driver's view prior to test
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre

**MOT #16**

2023-08-16 10:22

MOT test number

991318192058

Result**✗ Failed**

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Parking brake inoperative on one side Nearside not working (1.4.1 (a))
- Advice** Offside Rear Nail in tyre
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Rear Nail in tyre
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 245/70/16 (5.2.3 (e))
- Fail** Exhaust emissions exceed manufacturer's specified limit tested @1.04 (8.2.2.2 (a))

MOT #15

2022-07-27 14:18

MOT test number

926225283720

Result**✓ Passed**

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Front Prop shaft missing
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Items removed from driver's view prior to test

**MOT #14**

2022-07-27 09:40

MOT test number

146033067734

Result**✗ Failed**

- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material By fuel tank (1.1.11 (c))
- Fail** Nearside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))
- Fail** Exhaust emissions exceed manufacturer's specified limit 1.04 (8.2.2.2 (a))
- Fail** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Prop shaft missing
- Fail** Offside Rear Brake pipe excessively corroded By fuel tank (1.1.11 (c))

MOT #13

2021-08-04 12:46

MOT test number

871725716327

Result**✓ Passed**

- Advice** 4x4 propshaft missing
- Advice** Brake pipe corroded, covered in grease or other material Front/rear (1.1.11 (c))

**MOT #12**

2021-08-02 12:00

MOT test number

825029194952

Result**✗ Failed****Minor**

Rear Registration plate lamp inoperative in the case of multiple lamps or light sources X1 (4.7.1 (b) (i))

Advice

4x4 propshaft missing

Advice

Brake pipe corroded, covered in grease or other material Front/rear (1.1.11 (c))

Fail

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #11

2020-08-26 09:21

MOT test number

924924938974

Result**✓ Passed****Advice**

Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))

Advice

Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Child seat fitted not allowing full inspection of adult belt

Advice

Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10

2020-02-26 14:56

MOT test number

786374436248

Result**✗ Failed****Fail**

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2019-02-19 08:18**MOT test number** 370604694762**Result** ✓ Passed

- Advice** Front prop shaft missing
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material all exposed steel pipes slightly corroded (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-02-16 11:18**MOT test number** 660825727236**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Brake pipe corroded, covered in grease or other material all exposed steel pipes slightly corroded (1.1.11 (c))
- Advice** Front prop shaft missing
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-01-25 11:58**MOT test number** 156229994694**Result** ✓ Passed**MOT #6** 2016-09-01 14:32**MOT test number** 721029852626**Result** ✓ Passed

**MOT #5** 2016-09-01 14:31**MOT test number** 102184991313**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2015-09-02 08:19**MOT test number** 781629627026**Result** ✓ Passed**MOT #3** 2014-08-29 14:07**MOT test number** 775821744252**Result** ✓ Passed**MOT #2** 2013-08-27 11:05**MOT test number** 208609033267**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-08-30 09:31**MOT test number** 178713642256**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 August 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	25 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	NX57MYW
Plate since	2019-03-28
Current registration	NX57MYW
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-03
Last registration	2023-08-18
Complete history	See info



Registration #1	2008-01-03	12 mi
Registration #2	2012-08-30	36.644 mi
Registration #3	2013-08-27	53.015 mi
Registration #4	2014-08-29	63.069 mi
Registration #5	2015-09-02	66.099 mi
Registration #6	2016-09-01	68.243 mi
Registration #7	2016-09-01	68.243 mi
Registration #8	2018-01-25	72.092 mi
Registration #9	2019-02-16	77.153 mi
Registration #10	2019-02-19	77.153 mi
Registration #11	2019-02-20	77.153 mi
Registration #12	2019-02-20	77.153 mi
Registration #13	2019-02-20	77.153 mi
Registration #14	2019-02-20	77.153 mi
Registration #15	2019-02-20	77.153 mi
Registration #16	2019-02-20	77.153 mi
Registration #17	2019-02-20	77.153 mi
Registration #18	2019-02-20	77.153 mi
Registration #19	2019-02-20	77.153 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Max. allowed weight	2640 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4CB729452