




report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-08-20
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	31
Total items failed	3

MOT #13	2023-08-18 09:39
MOT test number	615460373584
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12	2022-08-19 11:38
MOT test number	466521946368
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #11	2021-09-07 17:36
MOT test number	423050276793
Result	✓ Passed

**MOT #10**

2021-08-26 06:11

MOT test number

818060405264

Result

✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Tyre has ply or cords exposed 205/55/16 (5.2.3 (d) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge also perished (5.2.3 (e))

MOT #9

2021-01-13 12:51

MOT test number

399435594397

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8

2020-01-04 10:34

MOT test number

575973056566

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inside face corroded (1.1.14 (a) (ii))
- Advice** Offside Front tyre bald inneredge
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inside face corroded (1.1.14 (a) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front tyre bald inner edge

**MOT #7** 2019-01-19 09:56**MOT test number** 689231725993**Result** ✓ Passed

- Advice** Noise on engine sounds like injector blowing
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face corroded (1.1.14 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face corroded (1.1.14 (a) (ii))

MOT #6 2018-02-02 16:30**MOT test number** 616726925136**Result** ✓ Passed

- Advice** Offside Front tyre inner edge badly worn looks close to cord level
- Advice** Nearside Front tyre low tread and worn edges
- Advice** Front brake discs corroded
- Advice** Offside Front driving orange side light in the side of the headlight not working

MOT #5 2016-12-16 16:15**MOT test number** 351714956263**Result** ✓ Passed**MOT #4** 2015-12-11 16:28**MOT test number** 175309674842**Result** ✓ Passed**MOT #3** 2015-01-05 11:51**MOT test number** 579825105033**Result** ✓ Passed



MOT #2	2014-01-13 10:35
MOT test number	835203214095
Result	✓ Passed
Advice	Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

MOT #1	2013-02-08 16:04
MOT test number	716309833093
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Inner Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BN10PWX
Plate since	2024-03-29
Current registration	BN10PWX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-19
Last registration	2023-08-18
Complete history	See info



Registration #1	2010-03-19	16 mi
Registration #2	2013-02-08	41.668 mi
Registration #3	2014-01-13	58.398 mi
Registration #4	2015-01-05	78.380 mi
Registration #5	2015-12-11	86.052 mi
Registration #6	2016-12-16	103.648 mi
Registration #7	2018-02-02	118.547 mi
Registration #8	2019-01-19	131.872 mi
Registration #9	2020-05-20	131.872 mi
Registration #10	2021-05-20	131.872 mi
Registration #11	2022-05-20	131.872 mi
Registration #12	2023-05-20	131.872 mi
Registration #13	2024-05-20	131.872 mi
Registration #14	2025-05-20	131.872 mi
Registration #15	2026-05-20	131.872 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602