





report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	143 Nm at 4.500 rpm
Engine capacity	1.599 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-02-18

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2020-11-06
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	20
Total items failed	20

MOT #	17	2021-06-01 11:50
MOT te	st number	761125609690
Result		★ Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	
Fail	Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 ((g) (ii))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3	3 (g) (ii))
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))	
Fail	Battery insecure and likely to cause a short circuit (4.13 (a) (ii))	

MOT #16	2019-11-04 12:05
MOT test number	938903882549
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

NV07DJX report date: 2024-03-29

× Failed

MOT #15 2018-10-23 11:18

MOT test number 932431345004

Result \rightarrow Passed

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #14 2018-10-23 11:18

MOT test number 832158002090

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13 2017-11-07 09:53

MOT test number 180403492854

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #12 2016-11-07 12:51

MOT test number 196923109280

Result

Passed

CarCheck.co.uk page 4/12



MOT #11

report date: 2024-03-29

2016-11-04 12:10

× Failed

MOT test number 851003463406 Result × Failed **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Offside Registration plate lamp insecure (1.1.C.1c) **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i) Advice Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b) Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail

Fail Offside Registration plate lamp not working (1.1.C.1d)

Front exhaust flexi pipe deteriorated **Advice**

Fail Rear fog lamp not working (1.3.2b)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #10 2015-11-05 09:07 **MOT** test number 682019083797

Result ✓ Passed

MOT #9 2015-11-04 16:17

MOT test number 920156146129 Result

Fail Offside Side repeater missing (1.4.A.2b)

MOT #8 2014-10-21 12:45 **MOT** test number 358934294416 ✓ Passed Result

CarCheck.co.uk page 5/12



MOT #7 2014-10-16 12:54

MOT test number 135839284269

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #6 2013-09-19 09:17

MOT test number 195142463258

Result ✓ Passed

MOT #5 2013-09-19 09:17

MOT test number 149112163215

Result X Failed

Pass with rectification Offside Windscreen washer provides insufficient washer liquid (8.2.3)

Pass with rectification Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #4 2012-10-17 11:25

MOT test number 795221992237

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside front brake juddering slightly (3.7.A.2b)

Notice Front to rear brake pipes covered

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Items removed from driver's view prior to test

Advice Offside front brake juddering slightly (3.7.A.2b)

CarCheck.co.uk page 6/12



MOT #3 2011-10-19 11:38

MOT test number 998312391236

Result ✓ Passed

MOT #2 2011-05-28 12:04

MOT test number 586768041100

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1 2010-06-07 17:28

MOT test number 181408850180

Result ✓ Passed

CarCheck.co.uk page 7/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-06-11
Last registration	2021-06-01
Complete history	See info



Registration #1	2007-06-11	16 mi
Registration #2	2010-06-07	34.547 mi
Registration #3	2011-05-28	43.838 mi
Registration #4	2011-10-19	46.942 mi
Registration #5	2012-10-17	56.285 mi
Registration #6	2013-09-19	63.601 mi
Registration #7	2014-10-16	83.262 mi
Registration #8	2014-10-21	83.262 mi
Registration #9	2015-11-04	97.369 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1256 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4ED7676195

CarCheck.co.uk page 12/12