





General information

Make	MINI
Model	MINI ONE
Colour	Blue
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1


Date Pictures 2021-02-02

10

Listing price

View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-08-28
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	24
Total items failed	10

MOT #17	2023-08-29 15:01
MOT test number	260897539261
Result	✓ Passed
Next expiry date	2024-08-28

MOT #16	2022-07-28 07:36
MOT test number	788037106758
Result	✓ Passed
Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	

MOT #15	2021-08-05 11:37
MOT test number	884810344787
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



MOT #14	2021-08-04 11:58
MOT test number	851501955461
Result	🗙 Failed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Rear Brake disc significantly and obviously worn inner face (1.1.14 (a) (i))	
Advice Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Fail Nearside Front Road wheel more than one fixing loose (5.2.1 (a) (ii))	

MOT #13	2019-09-19 15:52
MOT test number	556166523995
Result	✓ Passed

MOT #12	2018-10-04 09:02
MOT test number	688624243067
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2017-10-09 13:41
MOT test number	507240136156
Result	✓ Passed
MOT #10	2017-10-06 16:39
MOT test number	315516315491
Result	✓ Passed



MOT #	9	2017-10-06 09:11
MOT te	st number	223453120556
Result		🗙 Failed
Fail	Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)	
Fail	Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)	

MOT #8		2017-02-06 16:32
MOT test	number	466688203052
Result		🗸 Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2017-01-31 12:48	
MOT test number	106084665686	
Result	🗙 Failed	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		
Fail Offside Front Front position lamp(s) not working (1.1.A.3b)		
Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)		
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Fail Central Stop lamp not working (1.2.1b)		
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		



SR11HME report date: 2024-03-28

MOT #6		2016-02-01 11:03
MOT test	number	707307394929
Result		Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

МОТ #5	2016-02-01 08:53
MOT test number	852255012569
Result	🗙 Failed
Fail Offside Rear Additional braking device wiring in poor condition (3.6.1.5)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4		2014-07-31 12:45
MOT test	number	128332914265
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2014-07-29 12:58
MOT test number	955700714244
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Brake fluid warning lamp illuminated (3.6.G.2)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #2	2013-12-06 16:44
MOT test number	428640543307
Result	✓ Passed
MOT #1	2013-11-06 16:25
MOT test number	359610913339
Result	🗙 Failed
Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weaker	ned (3.5.1i)
Notice O/s/r brake has slight bind	
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting (2.4.G.2)	g in excessive movement
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakene	ed (3.5.1i)



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 28 August 2024	✓ MOT
Tax status			Valid until 1 August
Days left			95
MOT expiry date			28 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



SR11HME report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-03-22
Last registration	2023-08-29
Complete history	See info



Registration #1	2011-03-22	21 mi
Registration #2	2013-11-06	24.077 mi
Registration #3	2013-12-06	24.077 mi
Registration #4	2014-07-29	33.124 mi
Registration #5	2014-07-31	33.133 mi
Registration #6	2016-02-01	45.925 mi
Registration #7	2016-02-01	45.925 mi
Registration #8	2017-01-31	48.500 mi
Registration #9	2017-02-06	48.516 mi
Registration #10	2017-10-06	49.232 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi



SR11HME report date: 2024-03-28

Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1735 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	A767J014