





report date: 2024-03-29

#### General information

Make	CITROEN
Model	DS4 VTI DSIGN
Colour	White
Year of manufacture	2014
Top speed	120 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	118 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 2

Date	2021-07-24
Pictures	31

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-07-16
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

MOT expiry date	2024-07-26
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	10
Total items failed	8

MOT #12	2023-07-26 14:45
MOT test number	415129580878
Result	<b>✓</b> Passed
Next expiry date	2024-07-26
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #11	2023-07-26 11:27
MOT test number	163535877704
Result	<b>X</b> Failed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))  Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #10		2022-07-20 12:11
MOT test	number	663256337481
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge of tread (5	5.2.3 (e))
Advice	Nearside Rear Nail in tyre	
Advice	Offside Rear Nail in tyre	

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #9** 2022-07-04 13:45

MOT test number 808442393263

Result X Failed

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #8 2021-07-27 15:52

**MOT test number** 946501390287

Result \square Passed

**MOT #7** 2021-07-23 14:16

**MOT test number** 467317633293

**Result** ★ Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #6 2020-09-04 12:06

**MOT test number** 821539695033

Result \( \sqrt{Passed} \)

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

**MOT test number** 238496682033

MOT #4 2019-09-13 15:36

MOT test number 613909492467

Result × Failed

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #3 2018-09-01 09:52

**MOT test number** 342279302970

Result \rightarrow Passed

MOT #2 2017-09-16 11:25

**MOT test number** 794951835757

**Result** ✓ Passed

MOT #1 2016-09-08 12:41

**MOT test number** 753338822809

**Result** ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	26 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history
---------------

Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full research	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NIP.
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-01-31
Last registration	2023-07-26
Complete history	See info



Registration #1	2014-01-31	20 mi
Registration #2	2016-09-08	9.720 mi
Registration #3	2017-09-16	12.425 mi
Registration #4	2018-09-01	16.616 mi
Registration #5	2019-09-13	20.984 mi
Registration #6	2019-09-20	20.989 mi
Registration #7	2020-09-04	23.644 mi
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		71,777 esi

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1755 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FHCP1977480

CarCheck.co.uk page 12/12