



HYUNDAI



AP57GOC


report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Black
Year of manufacture	2007
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	130 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-06-22
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-07
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	20
Total items failed	1

MOT #15 2023-06-27 14:51

MOT test number 543286147871

Result ✓ Passed

Next expiry date 2024-07-07

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Underside corroded**Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2022-06-23 09:11

MOT test number 943568949586

Result ✓ Passed

MOT #13 2021-07-08 15:50

MOT test number 459672988158

Result ✓ Passed**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2020-09-05 09:31**MOT test number** 300069865755**Result** ✓ Passed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated STRONG ADVISE (6.1.7 (g) (i))

Advice Tyre slightly damaged/cracking or perishing both rear cracking (5.2.3 (d) (ii))

Minor Headlamp lens slightly defective both (4.1.1 (b) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11 2019-09-06 12:28**MOT test number** 549189648688**Result** ✓ Passed

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MOT #10 2018-09-05 16:41**MOT test number** 213009254255**Result** ✓ Passed**MOT #9** 2017-09-06 08:13**MOT test number** 876694527859**Result** ✓ Passed**MOT #8** 2016-09-07 14:09**MOT test number** 800348028911**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

**MOT #7** 2015-08-10 08:01**MOT test number** 967012125276**Result** ✓ Passed**Notice** Small cracks in both rear tyer treads**MOT #6** 2014-08-15 13:19**MOT test number** 145437024228**Result** ✓ Passed**MOT #5** 2013-06-10 08:00**MOT test number** 575391363109**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-05-16 11:07**MOT test number** 907877632104**Result** ✓ Passed**MOT #3** 2011-09-16 11:20**MOT test number** 345929051484**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-09-16 11:20
MOT test number	688849851294
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-09-16 12:31
MOT test number	542759550248
Result	✓ Passed
Notice	Both front tyres worn/wearing on inner edge
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-22
Last registration	2023-06-27
Complete history	See info



Registration #1	2007-09-22	20 mi
Registration #2	2010-09-16	15.929 mi
Registration #3	2011-09-16	20.505 mi
Registration #4	2012-05-16	23.763 mi
Registration #5	2013-06-10	28.482 mi
Registration #6	2014-08-15	32.738 mi
Registration #7	2015-08-10	40.280 mi
Registration #8	2016-09-07	59.982 mi
Registration #9	2017-09-07	75.277 mi
Registration #10	2018-09-07	90.572 mi
Registration #11	2019-09-07	105.867 mi
Registration #12	2020-09-07	121.162 mi
Registration #13	2021-09-07	136.457 mi
Registration #14	2022-09-07	151.752 mi
Registration #15	2023-06-27	167.047 mi
Registration #16	2024-03-29	182.342 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4HG7308715