



PNI2E0U

report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-01-11
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	22
Total items failed	11

MOT #12	2023-01-10 16:18
MOT test number	497801334188
Result	✓ Passed
Next expiry date	2024-01-11

MOT #11	2022-01-12 15:36
MOT test number	931906474795
Result	✓ Passed

MOT #10	2020-07-09 14:50
MOT test number	315688520545
Result	✓ Passed

**MOT #9**

2019-08-28 12:15

MOT test number

110145273608

Result

✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2019-08-21 10:04

MOT test number

779528812427

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #7**

2018-08-28 09:45

MOT test number

916939439689

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

2018-08-28 09:45

MOT test number

951230948669

Result

✗ Failed

Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))

Pass with rectification

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2017-08-26 10:18

MOT test number

335338912102

Result

✓ Passed

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Parking brake lever has little reserve travel (3.1.6b)

**MOT #4** 2017-08-26 10:18**MOT test number** 143089888379**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #3** 2016-08-30 13:03**MOT test number** 976429717488**Result** ✓ Passed**MOT #2** 2015-08-14 10:12**MOT test number** 648546625299**Result** ✓ Passed**MOT #1** 2015-03-06 14:41**MOT test number** 145095765024**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** All four tyres cracking in centre tread



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✗
MOT

Expired:
11 January 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	11 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-03-28
Current registration	 
Plate since	2019-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-11
Last registration	2023-01-10
Complete history	See info



Registration #1	2012-03-11	26 mi
Registration #2	2015-03-06	37.306 mi
Registration #3	2015-08-14	45.544 mi
Registration #4	2016-08-30	59.418 mi
Registration #5	2017-08-26	77.446 mi
Registration #6	2017-08-26	77.446 mi
Registration #7	2018-08-28	98.943 mi
Registration #8	2019-01-01	115.000 mi
Registration #9	2019-01-01	115.000 mi
Registration #10	2019-01-01	115.000 mi
Registration #11	2019-01-01	115.000 mi
Registration #12	2019-01-01	115.000 mi
Registration #13	2019-01-01	115.000 mi
Registration #14	2023-01-10	115.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1050 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	K12B-1407482