



General information

Make	MINI
Model	COOPER SD COOPER
Colour	Silver
Year of manufacture	2012
Top speed	119 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	114 g/km
CO2 label	C





MOT history

MOT expiry date	2025-02-19
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	26
Total items failed	9

MOT #12	2024-01-24 09:02
MOT test number	362104227896
Result	✓ Passed
Next expiry date	2025-02-19
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake pipe corroded, covered in grease or other material BOTH (1.1.11 (c))

MOT #11	2023-02-20 13:25
MOT test number	865690507091
Result	✓ Passed

MOT #10	2023-02-20 11:47
MOT test number	242576859457
Result	✗ Failed
Fail	Emission control equipment obviously defective No1 injector leaking seal (8.2.2.1 (a))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Inner edge (5.2.3 (d) (ii))



MOT #9	2020-08-25 08:33
MOT test number	468363867221
Result	✓ Passed

MOT #8	2019-09-11 18:21
MOT test number	319979997094
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (Inner Edge) (5.2.3 (e))
Advice	Undertray Fitted both sides

MOT #7	2018-09-13 16:03
MOT test number	681378190872
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear subframe surface corrosion

**MOT #6**

2018-09-07 08:18

MOT test number

851432049116

Result**✗ Failed**

- Advice** Rear subframe surface corrosion
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm worn down to canvas metal cords showing (5.2.3 (e))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #5

2017-09-06 13:04

MOT test number

617203404542

Result**✓ Passed**

- Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Central Front Stop lamp has light sources not illuminating, but not more than 50% has one of the lights not working (1.2.1b)

**MOT #4** 2017-09-05 07:44**MOT test number** 552743317807**Result** ✗ Failed

Advice Central Front Stop lamp has light sources not illuminating, but not more than 50% has one of the lights not working (1.2.1b)

Fail Nearside Front Inner Road wheel bead rim badly distorted (4.2.A.1a)

Fail Offside Front Shock absorber has a serious fluid leak (2.7.3)

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #3 2016-09-06 15:17**MOT test number** 559785076244**Result** ✓ Passed

Advice Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #2 2016-09-06 15:17**MOT test number** 513401727051**Result** ✗ Failed

Pass with rectification Offside Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)

Advice Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1 2015-09-01 00:00**MOT test number** 722795317113**Result** ✓ Passed

Advice Under trays fitted not allowing full view of some components

Advice Engine covers fitted not allowing full view of some components



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	19 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	RV62YUY
Plate since	2019-03-29
Current registration	RV62YUY
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-06
Last registration	2024-01-24
Complete history	See info



Registration #1	2012-09-06	10 mi
Registration #2	2015-09-01	27.355 mi
Registration #3	2016-09-06	39.622 mi
Registration #4	2016-09-06	39.622 mi
Registration #5	2017-09-05	50.449 mi
Registration #6	2017-09-06	50.449 mi
Registration #7	2018-09-07	62.015 mi
Registration #8	2019-09-07	73.581 mi
Registration #9	2020-09-07	85.147 mi
Registration #10	2021-09-07	96.713 mi
Registration #11	2022-09-07	108.279 mi
Registration #12	2023-09-07	119.845 mi
Registration #13	2024-01-24	130.411 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1205 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	A430I532
---------------	----------