





## General information

Make	NISSAN
Model	PRIMASTAR DCI E SHR P/V
Colour	White
Year of manufacture	2011
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	113 BHP	0 < 101 A
Engine capacity	1.995 cc	101 - 120 B
Cylinders	4	121 - 140 E
uel type	Diesel	141 - 165 F G
		166 - 185

225+



# Internet history

Entry 1	
Date	2021-07-29
Pictures	12
Listing price	View report





source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-03
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	10

MOT #15	2023-08-01 15:57
MOT test number	194314729305
Result	✓ Passed
Next expiry date	2024-08-03

MOT #14	2023-08-01 08:46	
MOT test number	772245169564	
Result	🗙 Failed	
Fail Nearside Parking brake inoperative on one side (1.4.1 (a))		
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))		

MOT #13	2022-07-29 07:58
MOT test number	329608678289
Result	✓ Passed



MOT #12	202	1-08-04 14:50
MOT test	number 5	53668638693
Result		🗸 Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14	(a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14	4 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))	

MOT #11	2021-08-02 12:32
MOT test number	663211801484
Result	🗙 Failed
<b>Fail</b> Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides	(1.1.14 (a) (ii))
Advice Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	
<b>Fail</b> Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides	; (1.1.14 (a) (ii))
Fail Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (i	i))

MOT #10	2020-10-07 09:43
MOT test number	482196415169
Result	✓ Passed





MOT #9	2019-10-04 16:12	
MOT test number	138145239046	
Result	✓ Passed	
MOT #8	2019-10-03 09:16	
<b>MOT test number</b> 384779453231		
Result	× Failed	
Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))		
<b>Fail</b> Front Track rod end ball joint has excessive play both sides (2.1.3 (b) (i))		

МОТ #7	2018-09-25 09:33
MOT test number	683799729963
Result	✓ Passed

MOT #6	2017-10-04 15:01
MOT test number	999774591819
Result	✓ Passed

MOT #5	2017-09-30 09:12
MOT test number	880554121167
Result	🗙 Failed
<b>Fail</b> Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
<b>Fail</b> Offside rear parking brake recording little or no effort (3.7.B.6a)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Advice Undertray fitted	





NOT #4		
MOT #4		2016-10-01 12:33
MOT test number		528165500406
Result		✓ Passed
Advice Engine co	ver & under trays fitted	
MOT #3		2015-09-28 08:50
MOT test number		773536878507
Result		✓ Passed
Advice Nearside (8.3.1d)	Front Upper Windscreen has damage to an area less th	aan a 40mm circle outside zone 'A'
MOT #2		2015-02-17 10:37
MOT test number		159798745072
Result		✓ Passed

MOT #1	2014-09-22 09:36
MOT test number	669785864209
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check







### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Law P
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	 ₩.
Category	 AMPT
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



EO61UZU report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-30
Last registration	2023-08-01
Complete history	See info



Registration #1	2011-09-30	24 mi
Registration #2	2014-09-22	66.213 mi
Registration #3	2015-02-17	77.055 mi
Registration #4	2015-09-28	93.345 mi
Registration #5	2016-10-01	116.640 mi
Registration #6	2017-09-30	141.742 mi
Registration #7	2017-10-04	141.753 mi
Registration #8	2018-09-25	151.973 mi
Registration #9	2019-10-03	156.998 mi
Registration #10		11.777 est
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



# Additional informationFuel deliveryDirect InjectionNumber of doors4Number of seats3Engine number115631