



HYUNDAI



WG18CZS


report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI SE
Colour	Blue
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2022-07-05
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-29
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #6 2024-04-25 15:30

MOT test number 980488153776

Result ✓ Passed

Next expiry date 2025-04-29

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2024-04-25 13:27

MOT test number 896602225581

Result ✗ Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #4 2023-04-26 09:24

MOT test number 175396453492

Result ✓ Passed

**MOT #3** 2022-03-30 14:17**MOT test number** 255198944384**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Under trays and engine covers fitted
- Advice** Offside Rear tyre inner edge wearing
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front tyre inner edge wearing

MOT #2 2022-03-28 12:10**MOT test number** 376178216632**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front tyre inner edge wearing
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Under trays and engine covers fitted
- Advice** Offside Rear tyre inner edge wearing

MOT #1 2021-04-27 09:56**MOT test number** 447895906448**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
29 April 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	29 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-04-30
Last registration	2024-04-25
Complete history	See info



Registration #1	2018-04-30	28 mi
Registration #2	2021-04-27	28.488 mi
Registration #3	2022-03-28	39.492 mi
Registration #4	2022-03-30	39.496 mi
Registration #5	2023-03-29	39.500 mi
Registration #6	2023-03-29	39.500 mi
Registration #7	2023-03-29	39.500 mi
Registration #8	2024-04-25	39.500 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	64%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1455 mm
Length	4340 mm
Wheel base	2650 mm
Kerb weight	1411 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBHZ173673