



RENAULT

DA60KBF


report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC I-MUSIC VVT
Colour	Silver
Year of manufacture	2010
Top speed	115 mph
0 - 100 km/h	11.7 seconds
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 109 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history


Entry 1

Date	2022-06-28
Pictures	1
Listing price	View report

AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-08-07
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	9
Total items failed	15

MOT #17	2023-08-08 13:59
MOT test number	184959391380
Result	✓ Passed
Next expiry date	2024-08-07

MOT #16	2023-08-08 11:22
MOT test number	943454002852

Result	✗ Failed
--------	----------

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Inner Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2022-08-01 10:02**MOT test number** 991387601178**Result** ✓ Passed**MOT #14** 2022-08-01 10:02**MOT test number** 343294215557**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13** 2021-11-25 16:12**MOT test number** 301566979451**Result** ✓ Passed**MOT #12** 2021-11-25 13:39**MOT test number** 463564055974**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2020-11-12 16:12**MOT test number** 676938457951**Result** ✓ Passed**MOT #10** 2019-11-08 13:43**MOT test number** 745967302784**Result** ✓ Passed

**MOT #9** 2019-11-05 12:08**MOT test number** 344378893298**Result** ✗ Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #8 2018-11-28 14:10**MOT test number** 741460938345**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-11-28 10:59**MOT test number** 173368855901**Result** ✗ Failed

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Insecure. (6.1.7 (g) (ii))

MOT #6 2017-11-28 15:40**MOT test number** 893279073309**Result** ✓ Passed

**MOT #5** 2017-11-28 11:02**MOT test number** 461078332167**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside rear brake binding (3.7.B.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-11-18 15:32**MOT test number** 799480335585**Result** ✓ Passed**MOT #3** 2015-11-18 14:11**MOT test number** 868377979202**Result** ✓ Passed**MOT #2** 2014-11-25 09:17**MOT test number** 119019424313**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-11-26 09:27**MOT test number** 887040633317**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	DA60KBF
Plate since	2019-03-28
Current registration	DA60KBF
Plate since	2019-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-11-30
Last registration	2023-08-08
Complete history	See info



Registration #1	2010-11-30	7 mi
Registration #2	2013-11-26	17.799 mi
Registration #3	2014-11-25	24.428 mi
Registration #4	2015-11-18	30.938 mi
Registration #5	2016-11-18	37.470 mi
Registration #6	2017-11-28	43.521 mi
Registration #7	2017-11-28	43.521 mi
Registration #8	2018-11-28	50.975 mi
Registration #9	2018-11-28	50.975 mi
Registration #10	2019-11-05	57.212 mi
Registration #11	2019-11-05	57.212 mi
Registration #12	2019-11-05	57.212 mi
Registration #13	2019-11-05	57.212 mi
Registration #14	2019-11-05	57.212 mi
Registration #15	2019-11-05	57.212 mi
Registration #16	2019-11-05	57.212 mi
Registration #17	2019-11-05	57.212 mi
Registration #18	2019-11-05	57.212 mi
Registration #19	2019-11-05	57.212 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1320 kg
Max. allowed weight	1877 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D051923