





report date: 2024-03-28

## General information

Make	MERCEDES-BENZ
Model	ML ML350 BLUETEC AMG SPORT
Colour	Silver
Year of manufacture	2014
Top speed	139 mph
0 - 100 km/h	7.4 seconds
Gearbox	7 speed automatic

## Engine & fuel consumption

Power	190 kW / 259 HP / 258 BHP
Max. torque	620 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	42.2 mpg
Consumption combined	39.2 mpg
CO2 emission	194 g/km
CO2 label	J



CarCheck.co.uk page 1/11



# Internet history

_	_	_		_	-
드	n	C	ľν	7	1

End y 1	
Date	2022-01-07
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2022-09-07
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	2

MOT #6		2021-09-08 09:06
MOT test	number	410573189457
Result		✓ Passed
Next exp	iry date	2022-09-07
Minor	Offside Rear reflector defective or damaged by up to 50% of the reflecting su	urface (4.8.1 (a) (i))
Minor Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))		
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #5		2020-09-03 10:05
MOT test	number	615512970846
Result		✓ Passed
Minor	Offside Rear reflector defective or damaged by up to 50% of the reflecting	surface (4.8.1 (a) (i))
Advice	Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Minor	Nearside Rear reflector defective or damaged by up to 50% of the reflecting	g surface (4.8.1 (a) (i))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping e	ffect (5.3.2 (b))

CarCheck.co.uk page 3/11



**MOT #4** 2019-08-30 12:20

**MOT test number** 703300209084

**Result** ✓ Passed

Minor Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-08-20 09:33

MOT test number 265487083667

**Result** X Failed

**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Fail Nearside Rear Body component damaged and likely to cause injury lamp lens (6.2.1 (a) (i))

**MOT #2** 2018-09-07 07:40

**MOT test number** 144043859293

Result 

Passed

MOT #1 2017-09-02 08:33

**MOT test number** 439287857469

Advice Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

(2.5.C.1a)

CarCheck.co.uk page 4/11



#### Tax & MOT check



Tax expired: 10 December 2021

# X MOT

**Expired:** 7 September 2022

Tax status	Expired at 10 December 2021
Days left	871 days too late
MOT expiry date	7 September 2022
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 5/11




### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES-BENZ salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

# Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report <u>here</u> .	
********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK NE
Plate since	

CarCheck.co.uk page 8/11



#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2014-02-11
Last registration	2021-09-08
Complete history	See info



Registration #1	2014-02-11	22 mi
Registration #2	2017-09-02	82.346 mi
Registration #3	2018-09-07	99.159 mi
Registration #4	2019-08-20	119.772 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

Registration #8

More info >

page 10/11 CarCheck.co.uk



## Car features

\$0295 \$0482 \$0501 \$0566	
S0501	
50566	
50567	
50569	

# Dimensions & weight

Width	1998 mm
Height	1796 mm
Length	4804 mm
Wheel base	2915 mm
Kerb weight	2175 kg
Max. allowed weight	2950 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64282641573350

CarCheck.co.uk page 11/11