



RENAULT

**Y898JAL**

report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC AUTHENTIQUE 16V SCENIC
Colour	Beige
Year of manufacture	2001
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-25
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-10-24
<b>MOT pass rate</b>	78 %
<b>MOT passed</b>	18
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	27
<b>Total items failed</b>	7

<b>MOT #23</b>	2023-10-18 13:32
<b>MOT test number</b>	795843531593
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-10-24

<b>MOT #22</b>	2022-10-25 15:01
<b>MOT test number</b>	273219431323
<b>Result</b>	✓ Passed

<b>MOT #21</b>	2021-10-05 10:44
<b>MOT test number</b>	670767367308
<b>Result</b>	✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

**Advice** O/S/R Tyre perished.

**Advice** N/S/R Tyre perished and worn close to the legal limit.

**MOT #20** 2021-10-01 15:01**MOT test number** 507435207753**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** O/S/R Tyre perished.**Fail** Windscreen washer not working (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** N/S/R Tyre perished and worn close to the legal limit.**MOT #19** 2020-12-08 15:45**MOT test number** 722320783415**Result** ✓ Passed**MOT #18** 2019-07-10 09:11**MOT test number** 468148249149**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #17** 2018-07-13 14:30**MOT test number** 423343680456**Result** ✓ Passed**MOT #16** 2017-07-07 13:26**MOT test number** 127333641219**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #15** 2017-07-07 09:23**MOT test number** 811694181494**Result** ✗ Failed**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #14** 2016-07-12 10:01**MOT test number** 219039015051**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake pads look low -suggest to get them checked**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #13** 2015-07-08 09:17**MOT test number** 726059985117**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2014-07-07 12:05**MOT test number** 279848984467**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #11**

2014-07-07 12:05

**MOT test number**

787028284158

**Result****✗ Failed****Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #10**

2013-07-08 10:21

**MOT test number**

127269183160

**Result****✓ Passed****Notice** All brake discs inner faces are corroded**MOT #9**

2012-07-02 10:22

**MOT test number**

255324782123

**Result****✓ Passed****Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** All the brake disc inner braking surfaces are corroding up**Notice** Lateral bar is corroded and holed**MOT #8**

2011-07-06 08:51

**MOT test number**

617877381112

**Result****✓ Passed**

**MOT #7** 2011-06-27 14:39**MOT test number** 987938571195**Result** ✗ Failed**Fail** Offside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**MOT #6** 2010-07-13 10:41**MOT test number** 813724690152**Result** ✓ Passed**Notice** Excessive corrosion on transverse mounting bracket at rear (non-structural).**MOT #5** 2010-07-13 09:26**MOT test number** 934574090113**Result** ✗ Failed**Notice** Excessive corrosion on transverse mounting bracket at rear (non-structural).**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2009-07-06 15:51**MOT test number** 292077789430**Result** ✓ Passed**MOT #3** 2008-07-03 09:32**MOT test number** 951225388133**Result** ✓ Passed**MOT #2** 2007-07-10 14:09**MOT test number** 651461697166**Result** ✓ Passed



MOT #1	2006-07-05 09:31
MOT test number	213116486156
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-




Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	Y898JAL
Plate since	2019-03-28
Current registration	Y898JAL
Plate since	2019-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	2024-03-28
Agreement type	RENT TO BUY
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-07-22
Last registration	2023-10-18
Complete history	<a href="#">See info</a>



Registration #1	2001-07-22	29 mi
Registration #2	2006-07-05	19.485 mi
Registration #3	2007-07-10	24.263 mi
Registration #4	2008-07-03	29.243 mi
Registration #5	2009-07-06	259.554 mi
Registration #6	2010-07-13	42.852 mi
Registration #7	2010-07-13	42.853 mi
Registration #8	2011-06-27	50.311 mi
Registration #9	2011-07-06	50.450 mi
Registration #10	2012-07-02	54.777 mi
Registration #11	2013-07-08	58.972 mi
Registration #12	2014-07-07	61.943 mi
Registration #13	2015-07-06	65.914 mi
Registration #14	2016-07-05	69.885 mi
Registration #15	2017-07-04	73.856 mi
Registration #16	2018-07-03	77.827 mi
Registration #17	2019-07-02	81.798 mi
Registration #18	2020-07-01	85.769 mi
Registration #19	2021-06-30	89.740 mi
Registration #20	2022-06-29	93.711 mi
Registration #21	2023-06-28	97.682 mi
Registration #22	2024-06-27	101.653 mi
Registration #23	2025-06-26	105.624 mi
Registration #24	2026-06-25	109.595 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2580 mm
Kerb weight	1250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D613127