



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 SE LUX D V50
Colour	Grey
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-03-15
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-09-06
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	36
Total items failed	12

MOT #20	2023-08-11 15:54
MOT test number	801495626225
Result	✓ Passed
Next expiry date	2024-09-06
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #19	2022-09-07 07:01
MOT test number	756768587979
Result	✓ Passed

MOT #18	2022-08-31 07:30
MOT test number	431487231953
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Exhaust emissions exceed level of metered smoke for a non-turbo charged engine (8.2.2.2 (b))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #17**

2021-11-03 15:41

MOT test number

821151448794

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #16

2021-11-03 09:11

MOT test number

817428056744

Result

✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #15

2020-11-16 14:47

MOT test number

578199452213

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2020-11-16 09:10

MOT test number

687461685762

Result**✗ Failed****Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13

2019-11-13 08:53

MOT test number

745635443151

Result**✓ Passed****Advice**

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2018-11-21 16:31

MOT test number

693671885571

Result**✓ Passed****MOT #11**

2018-03-13 11:02

MOT test number

780942917641

Result**✓ Passed****Advice**

Nearside Rear Rear reflector slightly deteriorated but function not impaired (1.5.1c)

**MOT #10**

2018-03-13 11:02

MOT test number

744717309451

Result**✗ Failed****Pass with rectification** Nearside Front Headlamp aim too low and too far to the right. (1.8)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Rear reflector slightly deteriorated but function not impaired (1.5.1c)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #9**

2017-03-16 12:32

MOT test number

836724957229

Result**✓ Passed****Advice** Front both tyres wearing on inner edges**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** N/s/f and n/s/r tyres have outer wall damage**MOT #8**

2017-03-16 12:32

MOT test number

947864443052

Result**✗ Failed****Advice** Front both tyres wearing on inner edges**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Pass with rectification** Nearside Front Headlamp aim too low and too far to the left. (1.8)**Advice** N/s/f and n/s/r tyres have outer wall damage

**MOT #7** 2016-03-29 10:11**MOT test number** 447931825959**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin o/s and n/s (3.5.1g)**Advice** Nearside Front tyre has outer wall damage**MOT #6** 2015-02-23 10:30**MOT test number** 778414155097**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2014-02-27 18:37**MOT test number** 129858254460**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2014-02-27 18:37**MOT test number** 287718354050**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #3	2013-03-04 15:34
MOT test number	906983163023
Result	✓ Passed

MOT #2	2012-02-24 10:27
MOT test number	506745352018
Result	✓ Passed
<div><div>Advice</div>Front Brake pad(s) wearing thin (3.5.1g)</div> <div><div>Advice</div>Rear Brake pad(s) wearing thin (3.5.1g)</div>	

MOT #1	2011-03-23 10:17
MOT test number	666452481059
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LJ08SPZ
Plate since	2019-09-28
Current registration	LJ08SPZ
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-06-27
Last registration	2023-08-11
Complete history	See info



Registration #1	2008-06-27	16 mi
Registration #2	2011-03-23	17.544 mi
Registration #3	2012-02-24	22.608 mi
Registration #4	2013-03-04	26.104 mi
Registration #5	2014-02-27	32.352 mi
Registration #6	2015-02-23	36.161 mi
Registration #7	2016-03-29	40.079 mi
Registration #8	2017-03-16	44.418 mi
Registration #9	2017-03-16	44.418 mi
Registration #10	2018-03-13	47.056 mi
Registration #11	2018-03-13	47.056 mi
Registration #12	2019-03-20	50.000 mi
Registration #13	2019-03-20	50.000 mi
Registration #14	2019-03-20	50.000 mi
Registration #15	2019-03-20	50.000 mi
Registration #16	2019-03-20	50.000 mi
Registration #17	2019-03-20	50.000 mi
Registration #18	2019-03-20	50.000 mi
Registration #19	2019-03-20	50.000 mi
Registration #20	2019-03-20	50.000 mi
Registration #21	2019-03-20	50.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1479 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

296839