



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	White
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2

Date	2022-02-16
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-15
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-13
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	10
Total items failed	2

MOT #13	2023-01-12 09:47
MOT test number	343201280786
Result	✓ Passed
Next expiry date	2024-01-13

MOT #12	2022-01-14 15:38
MOT test number	129153938386
Result	✓ Passed

MOT #11	2022-01-14 11:54
MOT test number	231912170596
Result	✗ Failed
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #10	2020-12-22 16:38
MOT test number	319458403546
Result	✓ Passed

**MOT #9** 2020-12-22 16:38**MOT test number** 384222036660**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2019-06-08 12:10**MOT test number** 823261340115**Result** ✓ Passed**MOT #7** 2019-06-08 07:57**MOT test number** 709302610631**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2018-07-02 08:11**MOT test number** 202137679542**Result** ✓ Passed**Advice** Offside Front Steering column top bearing slightly worn (2.2.2 (b))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #5** 2017-07-05 10:51**MOT test number** 841933678355**Result** ✓ Passed



MOT #4 2017-05-22 07:25

MOT test number 658227751247

Result ✓ Passed

MOT #3 2017-05-19 09:02

MOT test number 542933184728

Result ✗ Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2 2016-07-29 14:03

MOT test number 667487352228

Result ✓ Passed

MOT #1 2015-07-08 10:26

MOT test number 688449585191

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

X

Untaxed

Tax expired:
14 January 2023

X

MOT

Expired:
13 January 2024

Tax status	Expired at 14 January 2023
Days left	470 days too late
MOT expiry date	13 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-14
Last registration	2023-01-12
Complete history	See info



Registration #1	2012-09-14	25 mi
Registration #2	2015-07-08	36.046 mi
Registration #3	2016-07-29	49.353 mi
Registration #4	2017-05-19	79.828 mi
Registration #5	2017-05-22	79.828 mi
Registration #6	2017-07-05	79.964 mi
Registration #7	2018-07-02	88.292 mi
Registration #8	2019-06-08	95.937 mi
Registration #9	2019-06-08	95.937 mi
Registration #10	2019-06-08	95.937 mi
Registration #11	2019-06-08	95.937 mi
Registration #12	2019-06-08	95.937 mi
Registration #13	2019-06-08	95.937 mi
Registration #14	2019-06-08	95.937 mi
Registration #15	2019-06-08	95.937 mi
Registration #16	2019-06-08	95.937 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2259719