



General information

| | |
|---------------------|----------------|
| Make | MINI |
| Model | MINI ONE D |
| Colour | White |
| Year of manufacture | 2010 |
| Top speed | 114 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 90 BHP |
| Max. torque | 215 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-21 |
| Pictures | 22 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-30 |
| MOT pass rate | 92 % |
| MOT passed | 11 |
| Failed MOT tests | 1 |
| Total advice items | 14 |
| Total items failed | 0 |

| | |
|------------------|--|
| MOT #12 | 2023-11-07 10:23 |
| MOT test number | 367904265059 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-30 |
| Advice | Emissions tested no reading |
| Minor | Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i)) |

| | |
|-----------------|-----------------------------|
| MOT #11 | 2022-11-28 09:58 |
| MOT test number | 234389527605 |
| Result | ✓ Passed |
| Advice | Emissions tested no reading |

| | |
|-----------------|--|
| MOT #10 | 2021-11-10 16:05 |
| MOT test number | 559530798195 |
| Result | ✓ Passed |
| Minor | Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #9 | 2020-11-30 15:57 |
| MOT test number | 204221123083 |
| Result | ✓ Passed |

**MOT #8** 2020-11-30 14:12**MOT test number** 445022186305**Result** ✗ Failed

DANGEROUS Nearside Rear Brake disc in such a condition that it is seriously weakened BADLY WORN
(1.1.14 (a) (ii))

MOT #7 2019-11-19 11:17**MOT test number** 297753429387**Result** ✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner side of disc /
back (1.1.14 (a) (ii))

MOT #6 2018-11-06 15:07**MOT test number** 864975201323**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2017-11-13 10:25**MOT test number** 822022533896**Result** ✓ Passed**MOT #4** 2016-11-11 14:29**MOT test number** 343258429424**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #3 | 2015-11-11 12:21 |
| MOT test number | 657754682729 |
| Result | ✓ Passed |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) |

| | |
|-----------------|--|
| MOT #2 | 2014-11-04 11:36 |
| MOT test number | 946528204325 |
| Result | ✓ Passed |
| Notice | Child seat fitted not allowing full inspection of adult belt |

| | |
|-----------------|------------------|
| MOT #1 | 2013-11-13 15:20 |
| MOT test number | 868647713354 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
30 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 305 |
| MOT expiry date | 30 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2010-11-30 |
| Last registration | 2023-11-07 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-11-30 | 17 mi |
| Registration #2 | 2013-11-13 | 13.759 mi |
| Registration #3 | 2014-11-04 | 19.007 mi |
| Registration #4 | 2015-11-11 | 24.149 mi |
| Registration #5 | 2016-11-11 | 30.738 mi |
| Registration #6 | 2017-11-13 | 36.705 mi |
| Registration #7 | 2018-11-06 | 40.513 mi |
| Registration #8 | 2019-11-07 | 45.277 mi |
| Registration #9 | 2020-11-07 | 50.041 mi |
| Registration #10 | 2021-11-07 | 54.805 mi |
| Registration #11 | 2022-11-07 | 59.569 mi |
| Registration #12 | 2023-11-07 | 64.333 mi |
| Registration #13 | 2024-03-29 | 69.097 mi |
| Registration #14 | 2024-03-29 | 73.861 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1683 mm |
| Height | 1407 mm |
| Length | 3723 mm |
| Wheel base | 2467 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1540 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 40 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | 71567632 |