



RENAULT



LYIONME

report date: 2024-03-28

General information

| | |
|---------------------|-------------------------|
| Make | RENAULT |
| Model | TRAFIC SL27 DCI S/R P/V |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 96 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 115 BHP |
| Max. torque | 290 Nm at 1.600 rpm |
| Engine capacity | 1.996 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 41.5 mpg |
| Consumption combined | 38.2 mpg |



LABEL UNKNOWN



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-31 |
| MOT pass rate | 60 % |
| MOT passed | 9 |
| Failed MOT tests | 6 |
| Total advice items | 47 |
| Total items failed | 24 |

| | |
|------------------|--|
| MOT #15 | 2023-11-01 07:30 |
| MOT test number | 178744254024 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-31 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Advice | Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |

**MOT #14**

2023-10-26 06:38

MOT test number

683602259238

Result**✗ Failed**

- Fail** Upper Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2022-03-24 18:20

MOT test number

192737690376

Result**✓ Passed**

- Advice** Nearside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12**

2022-03-24 18:20

MOT test number

509700479542

Result**✗ Failed****Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Headlamp aim too high both (4.1.2 (a))**MOT #11**

2020-12-09 17:22

MOT test number

912923699057

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front top mount has movement when turning**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2020-12-09 13:48

MOT test number

741647171006

Result**✗ Failed**

- Fail** Brake cable damaged front section snapped unable to test on brake tester (1.1.15 (a))
- Fail** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Rear Stop lamp(s) not working centre lamp (4.3.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front top mount has movement when turning
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

MOT #9

2019-09-03 14:38

MOT test number

231031840530

Result**✓ Passed**

- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8** 2019-09-03 10:34**MOT test number** 800656358049**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Rear reflector missing (4.8.2 (a) (ii))**MOT #7** 2018-08-09 11:49**MOT test number** 516716567116**Result** ✓ Passed**MOT #6** 2018-08-09 08:27**MOT test number** 865701473869**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Rear Position lamp not working (4.2.1 (a))

**MOT #5** 2016-09-06 09:06**MOT test number** 118798211541**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Nail in tyre

MOT #4 2016-09-05 08:33**MOT test number** 663380545017**Result** ✗ Failed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Nail in tyre
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)



| | |
|-----------------|---|
| MOT #3 | 2015-07-20 16:16 |
| MOT test number | 949541005243 |
| Result | ✓ Passed |
| Advice | Offside Macpherson strut has slight movement at the upper attachment (2.5.A.1c) |

| | |
|-----------------|------------------|
| MOT #2 | 2014-07-15 16:06 |
| MOT test number | 907566894174 |
| Result | ✓ Passed |

| | |
|-----------------|------------------------------|
| MOT #1 | 2014-01-28 15:04 |
| MOT test number | 666568424063 |
| Result | ✓ Passed |
| Notice | Damage offside rear bodywork |



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
31 October 2024

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 May |
| Days left | | 1 |
| MOT expiry date | | 31 October 2024 |
| Full MOT history | | See MOT history |



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2019-01-01 |
| Current registration | XXXXXX |
| Plate since | 2019-01-01 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | |
|-------------------|-----------------|
| Finance company | RENAULT FINANCE |
| Date of agreement | 01/01/2024 |
| Agreement type | FINANCE |
| Agreement term | 36 months |
| Agreement number | 123456789 |
| Contact info | 0123 456789 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2010-07-23 |
| Last registration | 2023-11-01 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-07-23 | 15 mi |
| Registration #2 | 2014-01-28 | 58.334 mi |
| Registration #3 | 2014-07-15 | 60.396 mi |
| Registration #4 | 2015-07-20 | 73.087 mi |
| Registration #5 | 2016-09-05 | 86.169 mi |
| Registration #6 | 2016-09-06 | 86.169 mi |
| Registration #7 | 2018-08-09 | 106.206 mi |
| Registration #8 | 2018-08-09 | 106.206 mi |
| Registration #9 | 2019-05-29 | 115.277 mi |
| Registration #10 | 2019-05-29 | 115.277 mi |
| Registration #11 | 2019-05-29 | 115.277 mi |
| Registration #12 | 2019-05-29 | 115.277 mi |
| Registration #13 | 2019-05-29 | 115.277 mi |
| Registration #14 | 2019-05-29 | 115.277 mi |
| Registration #15 | 2019-05-29 | 115.277 mi |
| Registration #16 | 2019-05-29 | 115.277 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | C091993 |