



report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER D
Colour	White
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-20
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	27
Total items failed	0

MOT #14	2023-12-23 09:59
MOT test number	427841132578
Result	✓ Passed
Next expiry date	2025-01-20

MOT #13	2023-01-21 09:54
MOT test number	613024073653
Result	✓ Passed
Advice	Slight wear on front brake discs
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Slight corrosion and wear on rear brake discs

MOT #12	2022-03-01 12:58
MOT test number	437055251846
Result	✓ Passed
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11** 2021-03-08 15:00**MOT test number** 335032836904**Result** ✓ Passed**MOT #10** 2020-10-14 14:01**MOT test number** 934093293570**Result** ✓ Passed**MOT #9** 2019-12-18 13:55**MOT test number** 297085007396**Result** ✓ Passed**MOT #8** 2019-12-18 09:37**MOT test number** 832182392376**Result** ✗ Failed**MAJOR** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #7** 2018-12-27 16:59**MOT test number** 278261787945**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 3mm very badly cracked and perished (5.2.3 (e))**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm very badly cracked and perished (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2018-12-27 15:51**MOT test number** 707866461230**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 3mm very badly cracked and perished (5.2.3 (e))**Advice** Items removed from driver's view prior to test**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm very badly cracked and perished (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))**MOT #5** 2017-12-06 11:24**MOT test number** 936684648350**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit worn outer edge (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Nail in tyre**MOT #4** 2016-12-08 14:17**MOT test number** 158964800856**Result** ✓ Passed**MOT #3** 2015-11-26 10:23**MOT test number** 861290075624**Result** ✓ Passed



MOT #2	2014-11-20 10:03
MOT test number	866234324338
Result	✓ Passed

MOT #1	2013-12-19 10:35
MOT test number	479613353474
Result	✓ Passed
<div><div>Advice</div>Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Advice</div>Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Notice</div>Under-trays fitted obscuring some underside components</div> <div><div>Advice</div>Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-29
Last registration	2023-12-23
Complete history	See info



Registration #1	2010-09-29	26 mi
Registration #2	2013-12-19	32.347 mi
Registration #3	2014-11-20	36.459 mi
Registration #4	2015-11-26	41.268 mi
Registration #5	2016-12-08	46.280 mi
Registration #6	2017-12-06	51.106 mi
Registration #7	2018-12-27	56.424 mi
Registration #8	2018-12-27	56.424 mi
Registration #9	2019-12-27	56.424 mi
Registration #10	2019-12-27	56.424 mi
Registration #11	2019-12-27	56.424 mi
Registration #12	2019-12-27	56.424 mi
Registration #13	2019-12-27	56.424 mi
Registration #14	2019-12-27	56.424 mi
Registration #15	2019-12-27	56.424 mi
Registration #16	2019-12-27	56.424 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70667572