



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO GP
Colour	White
Year of manufacture	2010
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





## MOT history

MOT expiry date	2023-05-04
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	21
Total items failed	30

MOT #12 2023-05-03 07:28

MOT test number 759484444719

Result ✗ Failed

**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Fail** Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MOT #11 2022-05-05 12:42

MOT test number 367367993478

Result ✓ Passed

**MOT #10**

2022-04-21 14:52

**MOT test number**

871372340326

**Result****✗ Failed**

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

**MOT #9**

2020-09-04 05:52

**MOT test number**

516872779417

**Result****✓ Passed**

- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Front front wiper blades worn
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2020-09-01 08:22

**MOT test number**

351312056956

**Result****✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Exhaust emissions likely to be affected by an exhaust leak front pipe blowing (8.2.1.1 (b))

**MOT #7**

2018-09-10 13:25

**MOT test number**

440075526942

**Result****✓ Passed**

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front exhaust bracket broke
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))



MOT #6	2018-09-10 13:25
MOT test number	582002694178
Result	✗ Failed
Advice	Front exhaust bracket broke
Pass with rectification	Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #5	2017-02-27 17:36
MOT test number	819680517087
Result	✓ Passed

**MOT #4**

2017-02-25 14:14

**MOT test number**

180580630076

**Result****✗ Failed**

- Fail** Offside Front Headlamp not working on main beam (1.7.5a)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Offside Front brake disc modified and seriously weakened (3.5.1n)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Front brake disc modified and seriously weakened (3.5.1n)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3**

2016-02-09 09:31

**MOT test number**

418396195909

**Result****✓ Passed**

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2**

2015-02-28 13:33

**MOT test number**

446919855094

**Result****✓ Passed**



MOT #1	2013-09-05 13:48
MOT test number	919518743267
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
5 May 2023

X

MOT

Expired:  
4 May 2023

Tax status	Expired at 5 May 2023
Days left	361 days too late
MOT expiry date	4 May 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-09-24
Last registration	2023-05-03
Complete history	<a href="#">See info</a>



Registration #1	2010-09-24	20 mi
Registration #2	2013-09-05	25.540 mi
Registration #3	2015-02-28	33.572 mi
Registration #4	2016-02-09	39.134 mi
Registration #5	2017-02-25	45.493 mi
Registration #6	2017-02-27	45.493 mi
Registration #7	2018-09-10	61.442 mi
Registration #8	2019-05-20	75.277 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	7063879