





report date: 2024-03-28

General information

Make	BMW
Model	435 435D XDRIVE M SPORT
Colour	Black
Year of manufacture	2014
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-09

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #10	2023-06-02 10:31
MOT test number	131236929147
Result	✓ Passed
Next expiry date	2024-06-01

MOT #9	2023-05-31 11:52
MOT test number	648394947563
Result	X Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #8		2022-05-21 12:14
MOT test	number	319825969114
Result		✓ Passed
MOT #7		2021-06-02 08:44
MOT test	number	850638181653
Result		✓ Passed
Advice	Nearside Rear Nail in tyre	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #6 2020-05-18 09:54

MOT test number 712968592726

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement push/pull (5.3.4 (a) (i))

Advice Central Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear bump stop split

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement push/pull (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #5 2019-04-30 10:33

MOT test number 395049052445

MOT #4 2019-02-05 15:32

MOT test number 905090127177

Result ✓ Passed

MOT #3 2018-01-31 12:23

MOT test number 555598600823

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Advise replacement of rear tyres

CarCheck.co.uk page 4/12



MOT #2 2018-01-31 09:52

MOT test number 603112675630

Result X Failed

Advice Advise replacement of rear tyres

Fail Rear registration plate character(s) incorrectly spaced (6.3.4a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Front registration plate character(s) incorrectly spaced (6.3.4a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2017-02-03 16:11

MOT test number 964046804337

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK NK
Plate since	
	More info

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-27
Last registration	2023-06-02
Complete history	See info



Registration #1	2014-03-27	22 mi
Registration #2	2017-02-03	43.020 mi
Registration #3	2018-01-31	65.042 mi
Registration #4	2018-01-31	45.043 mi
Registration #5	2019-02-05	84.962 mi
Registration #6	2019-04-30	88.448 mi
Registration #7		9.70 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		77.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1825 mm
Height	1392 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1625 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 33239049