





General information

Make	RENAULT
Model	MEGANE SCENIC SPORT 16V
Colour	Green
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.7 mpg





Internet history

Entry 1

Date Pictures 2021-10-15

19

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #19	2021-10-19 10:26
MOT test number	307478824982
Result	✓ Passed
Next expiry date	2022-10-18

MOT #18		2021-10-19 10:26
MOT test number		185473721998
Result		× Failed
Pass with rectification	Rear Registration plate insecure (0.1 (a))	

MOT #17		2020-12-01 16:11
MOT test	number	835392562766
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Exhaust has a minor leak of exhaust gases Rear silencer corroded. (6.1.2 (a))	
Advice	Brake disc worn, but not excessively BOTH FRONT (1.1.14 (a) (i))	

MOT #16	2020-12-01 16:11
MOT test number	416506519119
Result	× Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice Oil leak, but not	excessive (8.4.1 (a) (i))
Advice Exhaust has a m	inor leak of exhaust gases Rear silencer corroded. (6.1.2 (a))
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification (4.2.3 (c))	Nearside Rear Position lamp adversely affected by the operation of another lamp
Advice Brake disc worn,	but not excessively BOTH FRONT (1.1.14 (a) (i))





MOT #15	2019-12-05 12:37
MOT test number	994622334581
Result	✓ Passed
MOT #14	2018-12-07 15:22
MOT test number	228009994173
Result	✓ Passed
MOT #13	2017-07-25 11:36
MOT test number	218979485368
Result	✓ Passed
MOT #12	2016-07-12 15:12
MOT test number	863276618173
Result	✓ Passed
MOT #11	2015-07-27 15:12
MOT test number	148738705256
Result	✓ Passed
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #10		2014-07-21 15:03
MOT test	number	567902304204
Result		✓ Passed
Advice	Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #9		2013-07-15 12:38
MOT test number		895476493124
Result		✓ Passed
MOT #8		2012-07-13 14:51
MOT test number		569865292156
Result		✓ Passed
MOT #7		2011-07-22 14:45
MOT test number		668093001229
Result		✓ Passed
МОТ #6		2010-07-16 16:28
MOT test number		844977090178
Result		✓ Passed
MOT #5		2010-07-16 16:28
MOT test number		213777990405
Result		🗙 Failed
	Nervide Deen Charleman activities (1.2.1k)	
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)	
MOT #4		2009-07-29 13:41
MOT test number		591640119226
Result		✓ Passed

MOT #3	2008-08-01 14:08
MOT test number	741104218231
Result	✓ Passed





MOT #2	2007-07-30 13:05
MOT test number	394611217442
Result	✓ Passed
MOT #1	2006-08-03 12:07
MOT test number	601415716298
Result	✓ Passed





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	1999-03-30
Last registration	2021-10-19
Complete history	See info



1999-03-30	29 mi
2006-08-03	24.628 mi
2007-07-30	25.798 mi
2008-08-01	26.239 mi
2009-07-29	26.937 mi
2010-07-16	27.466 mi
2011-07-22	27.910 mi
2012-07-13	28.217 mi
2013-07-15	28.839 mi
2014-07-21	29.372 mi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 mi
	11.777 mi
	2006-08-03 2007-07-30 2008-08-01 2009-07-29 2010-07-16 2011-07-22 2012-07-13 2013-07-15 2014-07-21







Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1752 mm
Height	1433 mm
Length	4508 mm
Wheel base	2670 mm
Additional information	
Additional information Fuel tank capacity	66 l
	66 I Multi-Point Injection
Fuel tank capacity	

D096101

Engine number