



Mercedes-Benz



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | MERCEDES |
| Model | CLK CLK280 SPORT |
| Colour | Blue |
| Year of manufacture | 2008 |
| Top speed | 150 mph |
| 0 - 60 mph | 7.8 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 228 BHP |
| Max. torque | 300 Nm at 3.000 rpm |
| Engine capacity | 2.996 cc |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 20.8 mpg |
| Consumption extra urban | 38.7 mpg |
| Consumption combined | 29.4 mpg |
| CO2 emission | 229 g/km |
| CO2 label | L |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-11 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-22 |
| MOT pass rate | 67 % |
| MOT passed | 12 |
| Failed MOT tests | 6 |
| Total advice items | 30 |
| Total items failed | 14 |

| | |
|------------------|---|
| MOT #18 | 2023-06-23 09:09 |
| MOT test number | 577737853857 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-22 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |

| | |
|-----------------|---|
| MOT #17 | 2022-01-18 16:53 |
| MOT test number | 450022507816 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #16**

2022-01-17 15:57

MOT test number

399437439263

Result

✗ Failed

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2021-01-21 16:30

MOT test number

736238699036

Result

✓ Passed

MOT #14

2021-01-20 12:59

MOT test number

404057526979

Result

✗ Failed

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure multiple splits in inner sidewall (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure multiple splits in inner sidewall (5.2.3 (d) (ii))**Fail** Offside Front Windscreen washer not working (3.5 (a))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure multiple splits in inner sidewall also on limit (5.2.3 (d) (ii))**Fail** Nearside Front Windscreen washer not working (3.5 (a))**Advice** Nearside Front Track rod end ball joint has slight play track rod arm inner has slight play (2.1.3 (b) (i))**MOT #13**

2020-01-22 16:29

MOT test number

793705797233

Result

✓ Passed

**MOT #12**

2020-01-22 11:01

MOT test number

673137018978

Result

✗ Failed

Fail

Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii))

Fail

Fuel cap/sealing device ineffective (6.1.3 (b) (i))

MOT #11

2019-01-21 09:39

MOT test number

257455011167

Result

✓ Passed

Advice

Covers impede parts of the inspection.

Advice

Offside front side lamp dim.

Advice

Possible crack in lower coil of offside rear suspension spring. Advise further inspection.

Advice

Offside door mirror glass discoloured.

Advice

Slight play in offside rear and nearside rear suspension lower wishbone outer joints/bushes.

MOT #10

2018-01-10 12:04

MOT test number

361154126106

Result

✓ Passed

Advice

Offside Front Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)

Advice

Offside Rear Rear reflector slightly deteriorated but function not impaired Damage to lens (1.5.1c)

**MOT #9** 2017-01-24 09:45**MOT test number** 461134667121**Result** ✓ Passed

- Advice** Rear exhaust hangar broken
- Advice** Offside mirror deteriorated
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake discs lipped
- Advice** Engine management light on

MOT #8 2016-01-27 11:03**MOT test number** 248921156789**Result** ✓ Passed

- Advice** Child seat fitted not allowing full inspection of adult seat belt

MOT #7 2016-01-27 11:03**MOT test number** 151112807154**Result** ✗ Failed

- Advice** Child seat fitted not allowing full inspection of adult seat belt
- Pass with rectification** Nearside Stop lamp not working (1.2.1b)

MOT #6 2015-01-09 12:17**MOT test number** 245169005097**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-01-16 17:02**MOT test number** 887266014060**Result** ✓ Passed**MOT #4** 2014-01-16 11:39**MOT test number** 689456514051**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #3** 2013-01-25 12:47**MOT test number** 477095723019**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2013-01-25 10:46**MOT test number** 408655123075**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-09-16 12:57**MOT test number** 168139451277**Result** ✓ Passed**Notice** Nearside rear tyre close to legal limit



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
22 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 154 |
| MOT expiry date | 22 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | L |
| Single payment (12 months) | £ 675,00,- |
| Single six month payment | £ 371,25,- |
| Total payable by 12 monthly instalments | £ 708,75,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|---|
| Number of plates | 7 |
| Current registration |  ***** |
| Plate since | 2023-03-29 |
| Current registration |  ***** |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2008-09-19 |
| Last registration | 2023-06-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2008-09-19 | 26 mi |
| Registration #2 | 2011-09-16 | 22.883 mi |
| Registration #3 | 2013-01-25 | 34.780 mi |
| Registration #4 | 2013-01-25 | 34.782 mi |
| Registration #5 | 2014-01-16 | 43.567 mi |
| Registration #6 | 2014-01-16 | 43.569 mi |
| Registration #7 | 2015-01-09 | 55.528 mi |
| Registration #8 | 2016-01-27 | 63.517 mi |
| Registration #9 | 2016-01-27 | 63.517 mi |
| Registration #10 | 2017-01-24 | 69.470 mi |
| Registration #11 | 2018-01-24 | 75.423 mi |
| Registration #12 | 2018-01-24 | 75.423 mi |
| Registration #13 | 2018-01-24 | 75.423 mi |
| Registration #14 | 2018-01-24 | 75.423 mi |
| Registration #15 | 2018-01-24 | 75.423 mi |
| Registration #16 | 2018-01-24 | 75.423 mi |
| Registration #17 | 2018-01-24 | 75.423 mi |
| Registration #18 | 2018-01-24 | 75.423 mi |
| Registration #19 | 2018-01-24 | 75.423 mi |
| Registration #20 | 2018-01-24 | 75.423 mi |

More info >



Dimensions & weight

| | |
|-------------|---------|
| Width | 1991 mm |
| Height | 1415 mm |
| Length | 4652 mm |
| Wheel base | 2690 mm |
| Kerb weight | 1705 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 27294030954540 |