



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Grey
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	144 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-12
Pictures	29
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-24
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	31
Total items failed	0

MOT #13	2023-11-25 17:18
MOT test number	938119247268
Result	✓ Passed
Next expiry date	2024-11-24
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #12	2022-05-11 13:35
MOT test number	785585722281
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11	2021-06-07 08:19
MOT test number	237428829502
Result	✓ Passed

**MOT #10**

2020-09-17 16:50

**MOT test number**

145053321431

**Result**

✓ Passed

- Advice** Rear Child Seat fitted not allowing full inspection of adult belt x2
- Minor** Front Windscreen damaged but not adversely affecting driver's view sml chips (3.2 (a) (i))
- Advice** Rear Shock absorbers has slight external damage to the casing x2 both sides (5.3.2 (b))
- Advice** Rear Window washer jet blocked
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Tyre slightly damaged/cracking or perishing O/s/f & O/s/r tyres cracking on outer shoulders (5.2.3 (d) (ii))

**MOT #9**

2020-09-17 13:41

**MOT test number**

664472166518

**Result**

✗ Failed

- MAJOR** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Shock absorbers has slight external damage to the casing x2 both sides (5.3.2 (b))
- Advice** Tyre slightly damaged/cracking or perishing O/s/f & O/s/r tyres cracking on outer shoulders (5.2.3 (d) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt x2
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Front Windscreen damaged but not adversely affecting driver's view sml chips (3.2 (a) (i))
- Advice** Rear Window washer jet blocked

**MOT #8**

2019-09-18 09:58

**MOT test number**

116985577911

**Result**

✓ Passed

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Shock absorbers has slight external damage to the casing both sides (5.3.2 (b))**Advice** Tyre slightly damaged/cracking or perishing o/s/r & o/s/f tyres perishing (5.2.3 (d) (ii))**MOT #7**

2018-09-12 07:30

**MOT test number**

813864815972

**Result**

✓ Passed

**Advice** Nearside Front Lower lower ball-joint boot starting to perish**Advice** Front Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))**MOT #6**

2017-09-09 09:07

**MOT test number**

544049470924

**Result**

✓ Passed

**MOT #5**

2016-09-19 14:07

**MOT test number**

962695129281

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front tyre worn on inner edge close to exposing cords**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front tyre worn on inner and outer edges close to exposing cords



<b>MOT #4</b>	2015-09-17 11:28
---------------	------------------

<b>MOT test number</b>	625991936064
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #3</b>	2014-09-08 12:03
---------------	------------------

<b>MOT test number</b>	228961454272
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2013-09-09 15:36
---------------	------------------

<b>MOT test number</b>	718732653291
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-09-04 15:15
---------------	------------------

<b>MOT test number</b>	175718342215
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
24 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	24 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GJ59OWA</b>
Plate since	2024-03-29
Current registration	 <b>GJ59OWA</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-16
Last registration	2023-11-25
Complete history	<a href="#">See info</a>



Registration #1	2009-09-16	24 mi
Registration #2	2012-09-04	44.150 mi
Registration #3	2013-09-09	54.946 mi
Registration #4	2014-09-08	63.652 mi
Registration #5	2015-09-17	77.603 mi
Registration #6	2016-09-19	92.974 mi
Registration #7	2017-09-09	107.337 mi
Registration #8	2018-09-12	113.184 mi
Registration #9	2019-09-12	113.184 mi
Registration #10	2020-09-12	113.184 mi
Registration #11	2021-09-12	113.184 mi
Registration #12	2022-09-12	113.184 mi
Registration #13	2023-09-12	113.184 mi
Registration #14	2024-03-29	113.184 mi
Registration #15	2024-03-29	113.184 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAX 206347