





report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC TDCI 125
Colour	Blue
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-05-24

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-31
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #15		2023-07-26 10:58
MOT test number		720822052534
Result		✓ Passed
Next expiry date		2024-07-31
Advice Nearside	Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside Re	ear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)))
Advice Rear Inne	er Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #14		2022-08-01 15:57
MOT test	number	893429273690
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	O/S/F tyre on 4mm tread	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #13	2021-07-31 10:54
MOT test number	911682766594
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2021-07-27 10:31

MOT test number 267664570252

Result X Failed

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #11 2020-06-25 14:06

MOT test number 637016426726

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement control arm T bush (5.3.4 (a) (i))

Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))

MOT #10 2020-06-18 11:15

MOT test number 211041191974

Result X Failed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement control arm T bush (5.3.4 (a) (i))

Fail Offside Rear Suspension arm pin or bush likely to become detached rear control arm T bush (5.3.4 (a) (ii))

Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))

MOT #9 2019-06-18 12:51

MOT test number 739896607656

Result
✓ Passed

MOT #8 2018-06-19 14:45

MOT test number 950581814610

Result \(\sqrt{Passed} \)

Advice Offside Rear main bush in poor condition

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number
742819398205

Result

Advice Front brake discs inner faces corroded

Advice Offside washer jet requires attention

Advice Offside wiper blade smears screen slightly

MOT #6

MOT test number

528268661664

Result

MOT #5

2016-06-14 11:53

2016-06-14 10:45

MOT test number

Result

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear tyre worn to legal limits

MOT #4

MOT test number

296377265113

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

Fesult

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

2014-06-19 12:04

537810074199

✓ Passed

CarCheck.co.uk page 5/13



MOT #2

MOT test number

Result

MOT #1

2013-06-19 12:41

468480173188

√ Passed

 MOT #1
 2012-06-21 15:22

 MOT test number
 447593572194

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-26
Last registration	2023-07-26
Complete history	See info



Registration #1	2009-06-26	15 mi
Registration #2	2012-06-21	30.677 mi
Registration #3	2013-06-19	38.630 mi
Registration #4	2014-06-19	46.469 mi
Registration #5	2015-06-16	51.656 mi
Registration #6	2016-06-14	57.876 mi
Registration #7	2016-06-14	57.876 mi
Registration #8	2017-06-13	62.667 mi
Registration #9	2018-06-19	67.971 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 mg

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2078 mm
Height	1457 mm
Length	4830 mm
Wheel base	2754 mm
Max. allowed weight	2265 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

9M61461