



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Grey
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2022-02-05
Pictures	18
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-02-04
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #14	2022-01-24 13:57
MOT test number	280144476084
Result	✓ Passed
Next expiry date	2023-01-23

MOT #13	2022-01-21 08:57
MOT test number	747350209661
Result	✗ Failed

Minor Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #12	2021-02-04 12:50
MOT test number	162243113977
Result	✓ Passed

MOT #11	2020-02-05 15:06
MOT test number	792593885439
Result	✓ Passed

MOT #10	2019-02-12 10:12
MOT test number	240152922636
Result	✓ Passed

MOT #9	2018-02-13 09:35
MOT test number	200128467659
Result	✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2017-02-21 09:43**MOT test number** 409925529283**Result** ✓ Passed**Advice** Rear exhaust mount broken**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Minor surface cracks to both rear tyres**MOT #7** 2016-02-16 10:36**MOT test number** 253869873821**Result** ✓ Passed**Advice** Both front tyres wearing on edges**MOT #6** 2015-02-10 10:42**MOT test number** 107851445027**Result** ✓ Passed**MOT #5** 2014-02-13 13:10**MOT test number** 778154044039**Result** ✓ Passed**Notice** Both front discs worn**Notice** Offside rear tyre cracking**MOT #4** 2013-02-01 14:03**MOT test number** 155112333015**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear wiper split



MOT #3	2012-02-17 15:48
MOT test number	825658042048
Result	✓ Passed
MOT #2	2011-02-14 12:17
MOT test number	149905841076
Result	✓ Passed
MOT #1	2011-02-14 12:17
MOT test number	875435041081
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	VF57LPX
Plate since	2019-09-28
Current registration	VF57LPX
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-02-28
Last registration	2022-01-24
Complete history	See info



Registration #1	2008-02-28	12 mi
Registration #2	2011-02-14	13.404 mi
Registration #3	2012-02-17	18.279 mi
Registration #4	2013-02-01	22.838 mi
Registration #5	2014-02-13	30.687 mi
Registration #6	2015-02-10	40.308 mi
Registration #7	2016-02-16	48.981 mi
Registration #8	2017-02-21	56.469 mi
Registration #9	2018-02-28	65.277 mi
Registration #10	2019-02-28	75.277 mi
Registration #11	2020-02-28	85.277 mi
Registration #12	2021-02-28	95.277 mi
Registration #13	2022-02-28	105.277 mi
Registration #14	2023-02-28	115.277 mi
Registration #15	2024-02-28	125.277 mi
Registration #16	2025-02-28	135.277 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBAW3003489