



HONDA




report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-VTEC ES GT
Colour	Silver
Year of manufacture	2009
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-02-13
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	23
Total items failed	7

MOT #17	2024-02-21 12:25
MOT test number	212051613162
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Rear axel coroded

MOT #16	2023-02-24 10:18
MOT test number	701224602468
Result	✓ Passed
Minor	Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2022-02-28 10:15
MOT test number	678204685062
Result	✓ Passed

MOT #14	2021-07-23 15:16
MOT test number	232834599452
Result	✓ Passed

**MOT #13**

2021-07-23 08:13

MOT test number

747607906974

Result**✗ Failed****Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2020-03-21 09:13

MOT test number

801347034606

Result**✓ Passed****Advice** Restricted view under the vehicle, under trays fitted**Advice** Restricted view of the outer sills, covers fitted**MOT #11**

2020-03-21 09:13

MOT test number

148257224179

Result**✗ Failed****Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Restricted view under the vehicle, under trays fitted**Advice** Restricted view of the outer sills, covers fitted**MOT #10**

2019-02-09 09:10

MOT test number

998302516449

Result**✓ Passed****Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9** 2019-02-02 10:51**MOT test number** 838850619167**Result** ✗ Failed**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2018-02-17 09:54**MOT test number** 180655420250**Result** ✓ Passed**MOT #7** 2017-02-28 09:59**MOT test number** 189857088224**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2016-02-29 10:02**MOT test number** 245688552027**Result** ✓ Passed**Advice** N/s front tyre cracking in treads**MOT #5** 2015-09-05 11:21**MOT test number** 380480377767**Result** ✓ Passed

**MOT #4**

2014-08-28 12:58

MOT test number

416200644287

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3

2014-08-22 12:06

MOT test number

469464834240

Result

✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

2013-08-21 13:53

MOT test number

71653333202

Result

✓ Passed



MOT #1	2012-08-21 09:50
MOT test number	345554032472
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-01
Last registration	2024-02-21
Complete history	See info



Registration #1	2009-09-01	9 mi
Registration #2	2012-08-21	27.085 mi
Registration #3	2013-08-21	30.704 mi
Registration #4	2014-08-22	34.058 mi
Registration #5	2014-08-28	34.215 mi
Registration #6	2015-09-05	37.955 mi
Registration #7	2016-02-29	39.981 mi
Registration #8	2017-02-28	43.047 mi
Registration #9	2018-02-17	47.267 mi
Registration #10	2019-02-02	53.352 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi
Registration #18	2019-05-29	55.377 mi
Registration #19	2019-05-29	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1414 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	R20A31109240