



RENAULT

YXIODVH

report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER LM35 LWB L/C P/V 100
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	260 Nm at 1.600 rpm
Engine capacity	2.464 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	36.2 mpg
Consumption combined	36.2 mpg





Internet history

Entry 1

Date	2022-05-29
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-25
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	30
Total items failed	17

MOT #17	2023-05-25 11:57
---------	------------------

MOT test number	982662852367
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-25
------------------	------------

- Advice** Rear Tyre slightly damaged/cracking or perishing n/s and o/s (5.2.3 (d) (ii))
- Advice** Rear Suspension spring mounting prescribed area is corroded but not considered excessive n/s and o/s (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Tyre slightly damaged/cracking or perishing n/s and o/s (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16**

2023-05-22 12:40

MOT test number

582811122576

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle 44% (1.2.1 (b) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Rear Suspension spring mounting prescribed area is corroded but not considered excessive n/s and o/s (5.3.6 (a) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing n/s and o/s (5.2.3 (d) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))
- Fail** Steering rack gaiter missing or no longer prevents the ingress of dirt n/s and o/s split (2.1.3 (g) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Fuel cap/sealing device ineffective temporary cap fitted (6.1.3 (b) (i))
- Advice** Front Tyre slightly damaged/cracking or perishing n/s and o/s (5.2.3 (d) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #15

2022-05-26 07:30

MOT test number

388927536825

Result**✓ Passed**

**MOT #14**

2021-04-01 12:50

MOT test number

104232432355

Result

✓ Passed

- Advice** Nearside Rear added brake light not working
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear add side light not working
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13

2021-04-01 08:51

MOT test number

247463741037

Result

✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Leaf spring to axle fixing bolt insecure u bolt (5.3.1 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear add side light not working
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear added brake light not working

MOT #12

2019-05-04 10:48

MOT test number

370228946717

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11** 2018-05-16 13:15**MOT test number** 842847929654**Result** ✓ Passed**MOT #10** 2018-05-15 12:46**MOT test number** 734264278940**Result** ✗ Failed

- Fail** Offside Front Ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Nearside Front Ball joint has excessive play (2.2.B.1f)

MOT #9 2017-06-22 17:13**MOT test number** 338185547604**Result** ✓ Passed**MOT #8** 2016-07-10 07:44**MOT test number** 764334568644**Result** ✓ Passed

- Advice** Offside Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)
- Advice** Nearside Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)

MOT #7 2015-07-05 17:25**MOT test number** 647116785173**Result** ✓ Passed**MOT #6** 2014-07-18 10:46**MOT test number** 996209594102**Result** ✓ Passed

**MOT #5** 2014-04-23 15:56**MOT test number** 215083114485**Result** ✓ Passed**MOT #4** 2014-04-14 13:39**MOT test number** 916154004196**Result** ✗ Failed**Fail** Nearside front brake application uneven (3.7.B.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside front brake excessively fluctuating (3.7.B.3)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #3** 2013-02-04 10:28**MOT test number** 488485833034**Result** ✓ Passed**Advice** Nearside Rear Lower Direction indicators slightly discoloured (1.4.A.2f)**MOT #2** 2012-02-06 10:07**MOT test number** 637907532062**Result** ✓ Passed**MOT #1** 2011-02-28 11:38**MOT test number** 865619551059**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 May 2024

Tax status		Valid until 1 June
Days left		33
MOT expiry date		25 May 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YX10DVH
Plate since	2019-03-29
Current registration	YX10DVH
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-11
Last registration	2023-05-25
Complete history	See info



Registration #1	2010-03-11	18 mi
Registration #2	2011-02-28	11.201 mi
Registration #3	2012-02-06	23.286 mi
Registration #4	2013-02-04	33.736 mi
Registration #5	2014-04-14	42.865 mi
Registration #6	2014-04-23	42.908 mi
Registration #7	2014-07-18	43.488 mi
Registration #8	2015-07-05	57.371 mi
Registration #9	2016-07-10	75.121 mi
Registration #10	2017-06-22	91.884 mi
Registration #11	2018-05-29	101.277 mi
Registration #12	2019-05-29	111.277 mi
Registration #13	2020-05-29	121.277 mi
Registration #14	2021-05-29	131.277 mi
Registration #15	2022-05-29	141.277 mi
Registration #16	2023-05-29	151.277 mi
Registration #17	2024-05-29	161.277 mi
Registration #18	2025-05-29	171.277 mi
Registration #19	2026-05-29	181.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1990 mm
Height	2489 mm
Length	5388 mm
Wheel base	4078 mm
Kerb weight	1937 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	C209864