



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTi
Colour	Silver
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-12
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-28
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	5
Total items failed	12

MOT #11	2024-01-29 12:23
MOT test number	894038356796
Result	✓ Passed
Next expiry date	2025-01-28
Minor	Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #10	2024-01-25 12:43
MOT test number	460136368698
Result	✗ Failed
Minor	Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Rear Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Rear Reversing lamp inoperative (4.6.1 (a))

MOT #9	2023-01-28 10:35
MOT test number	248220284495
Result	✓ Passed

**MOT #8** 2022-01-13 12:50**MOT test number** 265398250585**Result** ✓ Passed**Advice** Front number plate damaged**MOT #7** 2022-01-12 12:38**MOT test number** 530345828404**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front number plate damaged**Advice** Offside Front suspension top mount rough in operation**MOT #6** 2021-03-31 13:47**MOT test number** 808975358535**Result** ✓ Passed**MOT #5** 2021-03-31 09:28**MOT test number** 760737740337**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4** 2020-02-29 09:30**MOT test number** 504495395048**Result** ✓ Passed



MOT #3	2019-02-28 15:19
MOT test number	276929602667
Result	✓ Passed

MOT #2	2019-02-28 12:48
MOT test number	704337998853
Result	✗ Failed
<div><div>Fail</div>Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))</div> <div><div>Fail</div>Offside Front Headlamp aim too high (4.1.2 (a))</div>	

MOT #1	2018-02-20 14:30
MOT test number	443570856068
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
28 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LF15ZDN
Plate since	2019-06-29
Current registration	LF15ZDN
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-16
Last registration	2024-01-29
Complete history	See info



Registration #1	2015-03-16	25 mi
Registration #2	2018-02-20	59.241 mi
Registration #3	2019-02-28	78.836 mi
Registration #4	2019-02-28	78.836 mi
Registration #5	2020-02-29	86.350 mi
Registration #6	2021-03-31	92.422 mi
Registration #7	2021-03-31	92.422 mi
Registration #8	2022-03-31	92.422 mi
Registration #9	2022-03-31	92.422 mi
Registration #10	2022-03-31	92.422 mi
Registration #11	2022-03-31	92.422 mi
Registration #12	2022-03-31	92.422 mi
Registration #13	2024-01-29	92.422 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005688130 LN9