





report date: 2024-03-28

General information

Make	FIAT
Model	PANDA MULTIJET CROSS
Colour	White
Year of manufacture	2016
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entr	. 1
EIIU	vт

Date	2022-01-12
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-24
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	6

MOT #7	2023-09-23 11:55
MOT test number	196033235062
Result	✓ Passed
Next expiry date	2024-09-24
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #6	2022-09-02 10:36
MOT test number	787280557397
Result	✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not resulting i bush (5.3.4 (a) (i))	n excessive movement Rear
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e	2))
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

MOT #5	2021-09-07 11:38
MOT test number	637479147129
Result	✓ Passed
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

× Failed

MOT #4 2020-09-25 10:13

MOT test number 602438956094

Result ✓ Passed

Advice Fro

Result

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2020-09-18 14:28

MOT test number 147333488126

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Fail Nearside Rear Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #2 2020-05-14 13:39

MOT test number 960335561813

Result X Failed

Fail Nearside Headlamp insecure (4.1.1 (c))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))

Fail Nearside Headlamp aim not tested (4.1.2 (b))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #1 2019-07-29 08:26

MOT test number 777266216044

Result ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	999-0-0
Current registration	UK SIR
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.5	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-08-02
Last registration	2023-09-23
Complete history	See info



Registration #1	2016-08-02	21 mi
Registration #2	2019-07-29	39.741 mi
Registration #3	2020-05-14	45.789 mi
Registration #4	2020-09-18	45.824 mi
Registration #5	2020-09-25	45.825 mi
Registration #6		71,777 ea
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1662 mm
Height	1657 mm
Length	3705 mm
Wheel base	2300 mm
Kerb weight	1155 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 1:

Number of axles 2

Engine number 5996785