





report date: 2024-03-28

General information

Make	AUDI
Model	A3 MPI S LINE
Colour	Blue
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/14



MOT history

MOT expiry date	2024-02-28
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	26
Total items failed	16

MOT #20		2023-02-28 12:27
MOT test number		693832020834
Result		✓ Passed
Next expiry date		2024-02-28
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		

MOT #19	20	022-03-01 14:27
MOT test	number	242895389981
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #18		2021-02-18 11:21
MOT test	number	507727103273
Result		✓ Passed
Advice Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))))

CarCheck.co.uk page 2/14



LV58RLU

report date: 2024-03-28

MOT test number

Fesult

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

2020-01-03 17:19

525022396688

7 Passed

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

264752581572

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 225/40/18 (5.2.3 (e))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15		2019-01-03 09:36
MOT test i	number	657055476508
Result		✓ Passed
Advice	Offside Rear Nail in tyre	
Advice	Nearside Front Slight damage to outer rim.	

CarCheck.co.uk page 3/14



MOT #14 2019-01-03 09:36

MOT test number 989933863934

Result X Failed

Advice Nearside Front Slight damage to outer rim.

Pass with rectification Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Nail in tyre

Pass with rectification Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #13 2018-01-03 10:47

MOT test number 683858107543

Result Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2018-01-03 10:47

MOT test number 796931830583

Result X Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #11 2017-01-03 15:24

MOT test number 489891467578

Result
✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit only just legal (on 2mm) (4.1.E.1)

CarCheck.co.uk page 4/14



MOT #10 2017-01-03 11:08

MOT test number 294177495619

Result X Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit only just legal (on 2mm) (4.1.E.1)

MOT #9 2015-12-17 09:15

MOT test number 424186354724

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2015-12-16 11:25

MOT test number 178961819699

Result × Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear coil spring broken (2.4.C.1a)

MOT #7 2015-01-02 12:05

MOT test number 138382905452

Result ✓ Passed

MOT #6 2015-01-02 10:14

MOT test number 639132005087

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 5/14



LV58RLU

report date: 2024-03-28

MOT #5

MOT test number

279338133399

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-12-03 10:03 **MOT** test number 439377133350 Result × Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Horn not a continuous or uniform sound (1.6.2e) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b) Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Brakes imbalanced across an axle (3.7.B.5b)

MOT #3

MOT test number

877018432376

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

Result

Pass with rectification

Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



MOT #1 2011-12-07 10:03

MOT test number 368821541383

CarCheck.co.uk page 7/14



Tax & MOT check



Tax expired: 31 January 2024 X MOT

Expired: 28 February 2024

Tax statusExpired at 31 January 2024Days left88 days too lateMOT expiry date28 February 2024Full MOT historySee MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		e?
manage of the same		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	NK SIE	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



LV58RLU

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-12-09
Last registration	2023-02-28
Complete history	See info



Registration #1	2008-12-09	22 mi
Registration #2	2011-12-07	26.610 mi
Registration #3	2012-12-03	37.219 mi
Registration #4	2013-12-03	51.760 mi
Registration #5	2013-12-04	51.760 mi
Registration #6	2015-01-02	64.627 mi
Registration #7	2015-01-02	64.627 mi
Registration #8	2015-12-16	75.563 mi
Registration #9	2015-12-17	75.564 mi
Registration #10	2017-01-03	89.503 mi
Registration #11		9.70 es
Registration #12		71.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1225 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

Engine number BSE755586