



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------|
| Make | MAZDA |
| Model | CX-5 D SPORT NAV PLUS |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 127 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 380 Nm at 1.800 rpm |
| Engine capacity | 2.191 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 128 g/km |
| CO2 label | D |






Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-10-18 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-17 |
| Pictures | 36 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-23 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 2 |

| | |
|------------------|--|
| MOT #4 | 2023-06-17 11:39 |
| MOT test number | 588248055209 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-23 |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

| | |
|-----------------|--|
| MOT #3 | 2023-06-17 08:22 |
| MOT test number | 700664073137 |
| Result | ✗ Failed |
| Fail | Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Fail | Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #2 | 2022-06-24 08:41 |
| MOT test number | 541963774628 |
| Result | ✓ Passed |



MOT #1 2021-09-06 12:04

MOT test number 867379455172

Result ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corroded, pads 5mm (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3-4mm, scrubbed inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3-4mm, scrubbed inner edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
23 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 23 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | RX68GCV |
| Plate since | 2024-03-28 |
| Current registration | RX68GCV |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2018-09-26 |
| Last registration | 2023-06-17 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-09-26 | 15 mi |
| Registration #2 | 2021-09-06 | 39.641 mi |
| Registration #3 | 2023-06-17 | 39.641 mi |
| Registration #4 | 2023-06-17 | 39.641 mi |
| Registration #5 | 2023-06-17 | 39.641 mi |
| Registration #6 | 2023-06-17 | 39.641 mi |
| Registration #7 | 2023-06-17 | 39.641 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 95% |
| Children | 80% |
| Pedestrian | 78% |
| Safety systems | 59% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1840 mm |
| Height | 1680 mm |
| Length | 4550 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1576 kg |
| Max. allowed weight | 2130 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 56 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | SH 30876058 |