



PEUGEOT



APO6ENL

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Silver
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	26
Total items failed	4

MOT #18 2023-08-16 13:57

MOT test number 929197161106

Result ✓ Passed

Next expiry date 2024-08-15

Advice Brake pipe corroded, covered in grease or other material both front to rear greased (1.1.11 (c))

Advice Items removed from driver's view prior to test

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MOT #17 2022-08-11 10:26

MOT test number 283160488259

Result ✓ Passed

Advice Play in steering rack inner joint(s) both

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

MOT #16 2021-07-29 08:01

MOT test number 507649967337

Result ✓ Passed

**MOT #15** 2020-08-12 14:47**MOT test number** 863494662811**Result** ✓ Passed**MOT #14** 2020-08-12 09:17**MOT test number** 563938393739**Result** ✗ Failed**MAJOR** Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))**MAJOR** Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))**MOT #13** 2019-04-12 08:09**MOT test number** 746020750425**Result** ✓ Passed**MOT #12** 2018-04-03 14:30**MOT test number** 614069384876**Result** ✓ Passed**Advice** Offside Inner Drag link end ball joint has slight play (2.2.B.1f)**Advice** Nearside Inner Drag link end ball joint has slight play (2.2.B.1f)**MOT #11** 2018-04-03 10:30**MOT test number** 738887483141**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Inner Drag link end ball joint has slight play (2.2.B.1f)**Advice** Nearside Inner Drag link end ball joint has slight play (2.2.B.1f)

**MOT #10** 2017-04-06 12:05**MOT test number** 513041514149**Result** ✓ Passed

- Advice** Play in steering rack inner joint(s)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Child Seat fitted not allowing full inspection of adult belt

MOT #9 2016-04-01 08:33**MOT test number** 963825056378**Result** ✓ Passed

- Advice** Child seat fitted
- Advice** Front slight play in both inner rack joints
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #8 2015-04-08 10:42**MOT test number** 945978695006**Result** ✓ Passed

- Notice** Oil leak
- Notice** Play in steering rack inner joint(s)

MOT #7 2014-04-09 12:08**MOT test number** 308489394044**Result** ✓ Passed**MOT #6** 2013-04-02 14:07**MOT test number** 345522993020**Result** ✓ Passed

- Notice** Rear exhaust box corroded

**MOT #5** 2013-04-02 11:46**MOT test number** 158172293457**Result** ✗ Failed**Fail** Offside front brake binding (3.7.B.1)**Notice** Rear exhaust box corroded**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front brake application uneven (3.7.B.2)**MOT #4** 2012-04-20 13:59**MOT test number** 115441512158**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2011-05-31 12:25**MOT test number** 256401551445**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #2** 2010-06-01 10:06**MOT test number** 834352650172**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #1** 2009-05-27 09:19**MOT test number** 122737149163**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-06-01
Last registration	2023-08-16
Complete history	See info



Registration #1	2006-06-01	8 mi
Registration #2	2009-05-27	18.444 mi
Registration #3	2010-06-01	23.169 mi
Registration #4	2011-05-31	29.075 mi
Registration #5	2012-04-20	34.414 mi
Registration #6	2013-04-02	42.362 mi
Registration #7	2013-04-02	42.364 mi
Registration #8	2014-04-09	46.958 mi
Registration #9	2015-04-08	51.023 mi
Registration #10	2016-04-01	55.101 mi
Registration #11	2016-04-01	55.101 mi
Registration #12	2016-04-01	55.101 mi
Registration #13	2016-04-01	55.101 mi
Registration #14	2016-04-01	55.101 mi
Registration #15	2016-04-01	55.101 mi
Registration #16	2016-04-01	55.101 mi
Registration #17	2016-04-01	55.101 mi
Registration #18	2016-04-01	55.101 mi
Registration #19	2016-04-01	55.101 mi
Registration #20	2016-04-01	55.101 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FST65298536