





report date: 2024-03-28

General information

Make	PEUGEOT
Model	PARTNER BLUE HDI S L1
Colour	Silver
Year of manufacture	2016
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-08-11


Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-29
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	17
Total items failed	10

MOT #9		2023-11-21 14:56
MOT test	number	446519155169
Result		✓ Passed
Next expi	ry date	2024-11-29
Advice	Rear Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))	
Advice	Rear Brake pad(s) wearing thin needs closer inspection wheels off (1.1.13 (a) (ii))
Advice	Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))	
Advice	Offside Front Nail in tyre	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



Advice

Fail

ML66XOC

report date: 2024-03-28

MOT #8 2023-11-21 09:51 **MOT** test number 839948144648 Result × Failed Fail Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii)) **Advice** Rear Brake pad(s) wearing thin needs closer inspection wheels off (1.1.13 (a) (ii)) Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Offside Front Nail in tyre Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Central Seat belt not functioning as intended jammed (7.1.2 (c)) Advice Rear Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7

MOT test number

906396996715

Result

✓ Passed

Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT test number

403963376654

Result

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2021-11-25 14:42

MOT test number 794790127628

MOT #4 2021-11-25 09:37

MOT test number 445999163721

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3 2020-11-16 10:16

MOT test number 894537127374

Result \rightarrow Passed

MOT #2 2020-11-16 10:16

MOT test number 687567026452

Result X Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #1 2019-11-12 09:14

MOT test number 122702087454

Result \(\sqrt{Passed} \)

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Intermitent noise in steering column

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 29 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



ML66XOC report date: 2024-03-28

Owner history

*		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		IGEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-11-30
Last registration	2023-11-21
Complete history	See info



Registration #1	2016-11-30	27 mi
Registration #2	2019-11-12	113.759 mi
Registration #3	2020-11-16	127.100 mi
Registration #4	2020-11-16	127.100 mi
Registration #5		11.777 es
Registration #6	2021-11-25	141.434 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		19.397 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1314 kg
Max. allowed weight	2170 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBHB0013409

CarCheck.co.uk page 12/12