




report date: 2024-03-29

General information

Make	AUDI
Model	Q3 TDI QUATTRO S LINE
Colour	Black
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	9.9 seconds
0 - 60 mph	8.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 175 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.9 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-15
Pictures	17
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-01-19
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	21
Total items failed	5

MOT #12	2024-01-20 13:15
MOT test number	430763661578
Result	✓ Passed
Next expiry date	2025-01-19
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Oil leak, but not excessive Rear diff (8.4.1 (a) (i))

MOT #11	2023-01-09 17:37
MOT test number	107986661206
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-01-07 12:47
MOT test number	552655125844
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Rear Nail in tyre

**MOT #9** 2022-01-12 09:38**MOT test number** 173630045760**Result** ✓ Passed**MOT #8** 2021-08-06 15:59**MOT test number** 960673269808**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2021-08-04 15:49**MOT test number** 408708336841**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2020-08-03 11:10**MOT test number** 245148216429**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #5** 2019-07-24 13:59**MOT test number** 647838797331**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**MOT #4** 2019-07-23 10:31**MOT test number** 424828463593**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**MOT #3** 2018-07-26 14:08**MOT test number** 368534384778**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Outer face (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Outer face (1.1.14 (a) (ii))**MOT #2** 2017-08-17 10:12**MOT test number** 208317014758**Result** ✓ Passed



MOT #1	2017-08-14 12:47
MOT test number	508922032407
Result	✗ Failed
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Front registration plate incorrect (6.3.1a)



Tax & MOT check

X

Untaxed

Tax expired:  
25 April 2024

✓

MOT

Expires:  
19 January 2025

Tax status	Expired at 25 April 2024
Days left	5 days too late
MOT expiry date	19 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-10-31
Last registration	2024-01-20
Complete history	<a href="#">See info</a>



Registration #1	2014-10-31	20 mi
Registration #2	2017-08-14	17.443 mi
Registration #3	2017-08-17	17.443 mi
Registration #4	2018-07-26	24.218 mi
Registration #5	2019-07-23	30.265 mi
Registration #6	2019-07-24	30.265 mi
Registration #7	2020-08-03	41.213 mi
Registration #8	2020-08-03	41.213 mi
Registration #9	2020-08-03	41.213 mi
Registration #10	2020-08-03	41.213 mi
Registration #11	2020-08-03	41.213 mi
Registration #12	2020-08-03	41.213 mi
Registration #13	2020-08-03	41.213 mi
Registration #14	2020-08-03	41.213 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	85%
Pedestrian	52%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2019 mm
Height	1608 mm
Length	4385 mm
Wheel base	2603 mm
Kerb weight	1545 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

