



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D3 DRIVE ES
Colour	Grey
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2022-02-27
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	34
Total items failed	2

MOT #12	2024-02-16 10:33
MOT test number	686477515539
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both wearing on inner edges (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #11	2024-02-16 10:33
MOT test number	852586216403
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both wearing on inner edges (5.2.3 (e))

**MOT #10**

2023-02-20 09:56

MOT test number

117997168933

Result

✓ Passed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Front Nail in tyre centre of tread

Advice

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor

Windscreen damaged but not adversely affecting driver's view stone chips (3.2 (a) (i))

MOT #9

2022-02-28 15:24

MOT test number

846476940684

Result

✓ Passed

MOT #8

2021-03-24 14:05

MOT test number

943537559141

Result

✓ Passed

Advice

Engine cover and belly pans fitted

Advice

Chip in windscreen

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7**

2021-03-23 12:01

MOT test number

527607637410

Result**✗ Failed**

- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Chip in windscreen
- Advice** Engine cover and belly pans fitted
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front marker light not working
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

2020-03-24 13:13

MOT test number

877368901423

Result**✓ Passed**

- Advice** Windscreen chipped

**MOT #5** 2019-03-20 12:05**MOT test number** 313876596316**Result** ✓ Passed

- Advice** Both rear tyres unevenly worn
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake disc worn, but not excessively both rear (1.1.14 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Brake disc worn, but not excessively both front (1.1.14 (a) (i))

MOT #4 2018-03-27 13:13**MOT test number** 778872652848**Result** ✓ Passed**MOT #3** 2017-03-29 12:42**MOT test number** 991058204284**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2016-03-30 08:40**MOT test number** 395169881400**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-03-24 12:50
MOT test number	185513185032
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-30
Last registration	2024-02-16
Complete history	See info



Registration #1	2012-03-30	14 mi
Registration #2	2015-03-24	55.839 mi
Registration #3	2016-03-30	70.145 mi
Registration #4	2017-03-29	85.081 mi
Registration #5	2018-03-27	101.132 mi
Registration #6	2019-03-20	116.911 mi
Registration #7	2020-03-24	134.261 mi
Registration #8	2021-03-20	151.511 mi
Registration #9	2022-03-20	168.761 mi
Registration #10	2023-03-20	186.011 mi
Registration #11	2024-03-20	203.261 mi
Registration #12	2025-03-20	220.511 mi
Registration #13	2026-03-20	237.761 mi
Registration #14	2027-03-20	255.011 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1756 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1161516