



report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI SE
Colour	Grey
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	320 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN

**MOT history****MOT #16**

2020-09-03 11:37

**MOT test number**

620464355540

**Result**

✓ Passed

**Next expiry date**

2021-09-02

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**Minor** Battery insecure but not likely to fall from carrier clamp missing (4.13 (a) (i))**Advice** Key or remote buttons do not open car**Advice** Offside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Car is very low on fuel**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Service indicator showing

**MOT #15**

2020-09-02 09:12

**MOT test number**

109681279043

**Result**

✗ Failed

- Fail** Nearside Front Outline marker lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Service indicator showing
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Key or remote buttons do not open car
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect bulb in wrong? (4.1.2 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Car is very low on fuel
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Minor** Battery insecure but not likely to fall from carrier clamp missing (4.13 (a) (i))

**MOT #14**

2019-08-09 11:26

**MOT test number**

734395279278

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #13**

2019-07-05 09:12

**MOT test number**

941756929257

**Result****✗ Failed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #12**

2018-06-22 15:39

**MOT test number**

600209858121

**Result****✓ Passed**

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11**

2018-06-20 09:39

**MOT test number**

517564854852

**Result****✗ Failed****Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Headlamp aim not tested (4.1.2 (b))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #10**

2017-04-18 10:36

**MOT test number**

941684333346

**Result****✓ Passed****Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Bonnet open light on**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9**

2017-04-18 10:36

**MOT test number**

212313845786

**Result****✗ Failed****Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Bonnet open light on**Pass with rectification** Headlamp aim beam image obviously incorrect both front (1.8.A.1b)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8**

2016-04-01 12:12

**MOT test number**

846862839736

**Result****✓ Passed**

**MOT #7** 2015-04-27 15:30**MOT test number** 646827415157**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-07-02 10:42**MOT test number** 809733884178**Result** ✓ Passed**MOT #5** 2013-07-01 14:02**MOT test number** 298772183403**Result** ✓ Passed**MOT #4** 2012-07-02 10:48**MOT test number** 825294382180**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-07-02 10:48**MOT test number** 876404282173**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-06-24 14:46**MOT test number** 988645371162**Result** ✓ Passed



MOT #1	2011-06-06 12:48
MOT test number	348697951161
Result	✓ Passed
Notice	Offside rear tyre 2mm - Goodyear 225/45R17W91
Notice	Offside front tyre 1.6mm along central tread - Goodyear 225/45R17W91
Notice	Nearside front tyre 1.6mm along central tread - Goodyear 225/45R17W91



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-06-09
Last registration	2020-09-03
Complete history	<a href="#">See info</a>



Registration #1	2008-06-09	15 mi
Registration #2	2011-06-06	76.635 mi
Registration #3	2011-06-24	76.738 mi
Registration #4	2012-07-02	92.747 mi
Registration #5	2013-07-01	106.768 mi
Registration #6	2014-07-02	120.107 mi
Registration #7	2015-04-27	122.178 mi
Registration #8	2016-04-01	133.421 mi
Registration #9	2016-05-20	133.421 mi
Registration #10	2016-05-20	133.421 mi
Registration #11	2016-05-20	133.421 mi
Registration #12	2016-05-20	133.421 mi
Registration #13	2016-05-20	133.421 mi
Registration #14	2016-05-20	133.421 mi
Registration #15	2016-05-20	133.421 mi
Registration #16	2016-05-20	133.421 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Kerb weight	1295 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	BXE 979560
---------------	------------