



report date: 2024-03-28

General information

| | |
|---------------------|----------------------------|
| Make | FIAT |
| Model | BRAVO MULTIJET DYNAMIC ECO |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 116 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 105 BHP |
| Max. torque | 290 Nm at 1.500 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-03 |
| Pictures | 8 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|--|
| MOT #15 | 2023-06-15 15:22 |
| MOT test number | 807585462931 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-14 |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|------------------------|--|
| MOT #14 | 2023-06-13 15:28 |
| MOT test number | 101049397590 |
| Result | ✗ Failed |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Windscreen washer provides insufficient washer liquid (3.5 (a)) |
| Fail | Front Service brake excessively fluctuating (1.2.1 (e)) |
| Fail | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) |

| | |
|------------------------|--|
| MOT #13 | 2022-06-07 16:31 |
| MOT test number | 238194147148 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) |

**MOT #12**

2021-03-18 16:41

MOT test number

877284464783

Result

✓ Passed

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Gearbox mounting defective
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front tyre wearing on edges

MOT #11

2021-03-15 14:58

MOT test number

370339028889

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn wishbone (5.3.4 (a) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front tyre wearing on edges
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn wishbone (5.3.4 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Gearbox mounting defective

**MOT #10**

2020-03-26 12:56

MOT test number

219817824280

Result

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Knock from front suspension-no fault found
- Advice** Offside Rear Brake pad(s) wearing thin advise replacement now (1.1.13 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front bodywork damaged
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Clutch pedal anti slip provision missing
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower rear bush worn/splitting (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre outer shoulder worn to zero (5.2.3 (e))
- Advice** Advise replacement front/rear brake pads /worn very low
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Outer sill panel damaged

**MOT #9** 2019-03-27 15:05**MOT test number** 944890346500**Result** ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front wing/bodywork damaged
- Advice** Central/rear exhaust clamp missing system secure/not leaking
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Outer sill panel damaged
- Advice** Offside Front noise/knock from suspension no fault found
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bush worn/perished (5.3.4 (a) (i))

MOT #8 2018-03-20 10:13**MOT test number** 969611085999**Result** ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Bolt missing from rear exhaust mount still supported by other mounts
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2016-11-23 11:46**MOT test number** 555758691182**Result** ✓ Passed

- Advice** O/s/f tyre wearing inner edge
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front inner surfaces (3.5.1i)

**MOT #6** 2016-11-23 11:46**MOT test number** 790210270112**Result** ✗ Failed

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm 205/55x16 (4.1.E.1)

Advice O/s/f tyre wearing inner edge

Advice Brake disc worn, pitted or scored, but not seriously weakened both front inner surfaces (3.5.1i)

MOT #5 2015-12-16 13:00**MOT test number** 306704556547**Result** ✓ Passed**MOT #4** 2015-12-15 14:08**MOT test number** 234098594044**Result** ✗ Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #3 2014-06-24 11:51**MOT test number** 649775274146**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #2 2013-06-19 12:54**MOT test number** 665420573105**Result** ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay



| | |
|-----------------|--|
| MOT #1 | 2012-06-26 11:24 |
| MOT test number | 519398372133 |
| Result | ✓ Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay |
| Notice | Under-trays fitted obscuring some underside components |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this FIAT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2009-06-29 |
| Last registration | 2023-06-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-06-29 | 12 mi |
| Registration #2 | 2012-06-26 | 40.340 mi |
| Registration #3 | 2013-06-19 | 46.681 mi |
| Registration #4 | 2014-06-24 | 52.800 mi |
| Registration #5 | 2015-12-15 | 64.334 mi |
| Registration #6 | 2015-12-16 | 64.335 mi |
| Registration #7 | 2016-11-23 | 70.777 mi |
| Registration #8 | 2016-11-23 | 70.777 mi |
| Registration #9 | 2018-03-20 | 76.278 mi |
| Registration #10 | 2019-06-20 | 82.777 mi |
| Registration #11 | 2019-06-20 | 82.777 mi |
| Registration #12 | 2019-06-20 | 82.777 mi |
| Registration #13 | 2019-06-20 | 82.777 mi |
| Registration #14 | 2019-06-20 | 82.777 mi |
| Registration #15 | 2019-06-20 | 82.777 mi |
| Registration #16 | 2019-06-20 | 82.777 mi |
| Registration #17 | 2019-06-20 | 82.777 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1792 mm |
| Height | 1498 mm |
| Length | 4336 mm |
| Wheel base | 2600 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1830 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 58 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|---------|
| Number of axles | 2 |
| Engine number | 6237400 |