





report date: 2024-03-28

## General information

| Make                | VOLKSWAGEN     |
|---------------------|----------------|
| Model               | JETTA SE TDI   |
| Colour              | Black          |
| Year of manufacture | 2007           |
| Top speed           | 117 mph        |
| 0 - 60 mph          | 11.9 seconds   |
| Gearbox             | 5 speed Manual |

# Engine & fuel consumption

| Power                   | 104 BHP             |
|-------------------------|---------------------|
| Max. torque             | 250 Nm at 1.900 rpm |
| Engine capacity         | 1.896 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 42.2 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 53.3 mpg            |
| CO2 emission            | 137 g/km            |
| CO2 label               | E                   |



CarCheck.co.uk page 1/14



report date: 2024-03-28

# Internet history

## Entry 1

Date 2021-08-09

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

| MOT expiry date    | 2024-07-26 |
|--------------------|------------|
| MOT pass rate      | 88 %       |
| MOT passed         | 15         |
| Failed MOT tests   | 2          |
| Total advice items | 28         |
| Total items failed | 2          |

| MOT #17          | 2023-07-26 14:35 |
|------------------|------------------|
| MOT test number  | 229461953975     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-07-26       |

| MOT #16  |  | 2022-07-27 08:25 |
|----------|--|------------------|
| MOT test | number   | 938552724694     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |

| MOT #15  | 2022-07-26 15:38 |  |
|--|------------------|--|
| MOT test number  | 493893186995     |  |
| Result   | <b>X</b> Failed  |  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) |                  |  |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |                  |  |

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #14** 2021-06-01 09:36

MOT test number 482871519252

**Result** ✓ Passed

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #13** 2020-06-17 10:37

**MOT test number** 351484006605

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #12 2019-06-18 12:18

MOT test number 151069006741

Result 

Passed

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #11** 2019-06-18 11:08

**MOT test number** 434947440735

Result X Failed

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #10** 2018-06-18 09:24

MOT test number 112135629350

Result 

Passed

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #9** 2017-06-19 09:34

MOT test number 500830360197

Result \( \sqrt{Passed} \)

**Advice** Front coil spring corroded Nearside and offside (2.4.C.1b)

**Advice** Slight perishing in the nearside and offside rear tyre treads

**Advice** Rear coil spring corroded Nearside and offside (2.4.C.1b)

MOT #8 2016-05-31 10:43

MOT test number 253725458463

**Result** ✓ Passed

**Advice** Coil spring corroded all (2.4.C.1b)

Advice Rear nearside offside tyre treads slight perishing

CarCheck.co.uk page 5/14



report date: 2024-03-28

| MOT #7   | 2015-06-18 11:38 |
|--|------------------|
| MOT test number  | 338609165151     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #6   | 2014-06-12 10:59 |
| MOT test number  | 226933264162     |
| Result   | ✓ Passed         |
| <b>Notice</b> Engine covers fitted obscuring some components in the engine bay |                  |
| Advice Front coil spring corroded (2.4.C.1b)                                   |                  |
| Notice Under-trays fitted obscuring some underside components                  |                  |

| MOT #5  | 2013-06-08 10:59 |
|---|------------------|
| MOT test number                                 | 388809053161     |
| Result  | <b>✓</b> Passed  |
| Advice Front Brake pad(s) wearing thin (3.5.1g) |                  |

| MOT #4          | 2012-06-22 08:55 |
|-----------------|------------------|
| MOT test number | 785004072157     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #3          | 2011-06-08 11:27 |
| MOT test number | 267109051438     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #2          | 2010-06-29 15:09 |
| MOT test number | 242780080157     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2010-04-14 09:52

**MOT test number** 143104400179

**Result** ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

# Tax & MOT check



| Tax status       | Valid until 1 June |
|------------------|--------------------|
| Days left        | 33                 |
| MOT expiry date  | 26 July 2024       |
| Full MOT history | See MOT history    |

## Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | Е          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 8/14



report date: 2024-03-28

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



| Owner history  |   |
|--|---|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. |   |
| ***************************************  |   |
|  |   |
| ***************************************  |   |
| ***************************************  |   |
|  |   |
| ***************************************  |   |
|  | More info >                             |
| Plate changes  |   |
| See in this check if this VOLKSWAGEN had different number plates.  |   |
| Number of plates   | ,                                       |
| Current registration   | NIE |
| Plate since  |   |
| Current registration   | AIR<br>AIR                              |
| Plate since  |   |
|  | More info >                             |
|  |   |

CarCheck.co.uk page 11/14



## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

**Contact info** 


More info >

CarCheck.co.uk page 12/14



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 19         |
| First mileage registration | 2007-04-23 |
| Last registration          | 2023-07-26 |
| Complete history           | See info   |



| Registration #1  | 2007-04-23 | 28 mi     |
|------------------|------------|-----------|
| Registration #2  | 2010-04-14 | 11.542 mi |
| Registration #3  | 2010-06-29 | 12.030 mi |
| Registration #4  | 2011-06-08 | 26.187 mi |
| Registration #5  | 2012-06-22 | 39.186 mi |
| Registration #6  | 2013-06-08 | 46.325 mi |
| Registration #7  | 2014-06-12 | 52.883 mi |
| Registration #8  | 2015-06-18 | 59.770 mi |
| Registration #9  | 2016-05-31 | 66.610 mi |
| Registration #10 | 2017-06-19 | 73.108 mi |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.117 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.177 mi |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | 0.00 44   |
| Registration #19 |            | 0.77      |

More info >

CarCheck.co.uk page 13/14



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1781 mm |
|---------------------|---------|
| Height              | 1459 mm |
| Length              | 4554 mm |
| Wheel base          | 2578 mm |
| Kerb weight         | 1508 kg |
| Max. allowed weight | 1940 kg |

# Additional information

| Fuel tank capacity | 55 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |
| CarChaelesaule     | no ao 14/14      |

CarCheck.co.uk page 14/14

| Number of seats | 5          |
|-----------------|------------|
| Number of axles | 2          |
| Engine number   | BXE 564359 |