



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Blue
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-08
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-09
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	18
Total items failed	11

MOT #20	2024-03-07 10:47
MOT test number	774008620033
Result	✓ Passed
Next expiry date	2025-03-09
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #19	2024-03-07 10:47
MOT test number	448683501447
Result	✗ Failed
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #18** 2023-03-10 15:33**MOT test number** 673590565068**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #17** 2023-03-09 14:34**MOT test number** 852400793347**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #16** 2022-03-09 14:18**MOT test number** 351897281165**Result** ✓ Passed**MOT #15** 2022-01-12 14:03**MOT test number** 649730892576**Result** ✓ Passed**MOT #14** 2020-10-12 09:11**MOT test number** 378313666997**Result** ✓ Passed**MOT #13** 2019-09-30 10:58**MOT test number** 595201011754**Result** ✓ Passed

**MOT #12** 2019-09-30 09:17**MOT test number** 440151088643**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11** 2018-07-30 09:41**MOT test number** 202506794771**Result** ✓ Passed**MOT #10** 2017-07-25 14:29**MOT test number** 780202344181**Result** ✓ Passed**MOT #9** 2017-07-25 10:37**MOT test number** 859472778142**Result** ✗ Failed**Fail** Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #8** 2016-07-14 08:34**MOT test number** 363652484917**Result** ✓ Passed**MOT #7** 2015-07-16 16:27**MOT test number** 108327795152**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-07-15 11:39**MOT test number** 447116794100**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2014-07-15 11:39**MOT test number** 896256894153**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-07-16 13:15**MOT test number** 275757393154**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-07-16 13:15**MOT test number** 519987693142**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-07-23 10:46**MOT test number** 935405402275**Result** ✓ Passed



MOT #1	2012-07-23 10:46
MOT test number	317495602432
Result	✗ Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 March 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	9 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YB09EKW
Plate since	2020-03-29
Current registration	 YB09EKW
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-07-30
Last registration	2024-03-07
Complete history	See info



Registration #1	2009-07-30	21 mi
Registration #2	2012-07-23	36.142 mi
Registration #3	2013-07-16	51.131 mi
Registration #4	2014-07-15	67.969 mi
Registration #5	2015-07-16	81.161 mi
Registration #6	2016-07-14	85.910 mi
Registration #7	2017-07-25	87.086 mi
Registration #8	2017-07-25	87.086 mi
Registration #9	2018-07-30	88.724 mi
Registration #10	2019-09-30	91.006 mi
Registration #11	2020-03-29	91.006 mi
Registration #12	2020-03-29	91.006 mi
Registration #13	2020-03-29	91.006 mi
Registration #14	2020-03-29	91.006 mi
Registration #15	2020-03-29	91.006 mi
Registration #16	2020-03-29	91.006 mi
Registration #17	2020-03-29	91.006 mi
Registration #18	2020-03-29	91.006 mi
Registration #19	2020-03-29	91.006 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629