





report date: 2024-03-28

General information

Make	HYUNDAI
Model	140 CRDI STYLE BLUE DRIVE
Colour	Black
Year of manufacture	2014
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С




CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-01-31
Pictures	10











source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-07
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	24
Total items failed	0

MOT #9	2024-01-08 15:25
MOT test number	376274008290
Result	✓ Passed
Next expiry date	2025-01-07
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #8	2024-01-06 11:45
MOT test number	978948379550
Result	X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



Advice

RJ64UBL report date: 2024-03-28

MOT #7 2022-12-31 09:40 955013327175 **MOT** test number ✓ Passed Result **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f)) Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6		2022-01-08 12:04
MOT test i	number	675010760031
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MOT #5		2020-12-31 10:16
MOT test	number	297291640752
Result		✓ Passed
MOT #4		2020-12-29 12:31
MOT test	number	533223851116
Result		× Failed
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2

MOT test number

931065887683

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Front Upper Windscreen damaged but not adversely affecting driver's view small chip/crack (3.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		ΑI
THE PARTY OF THE P		

	More info >	
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK GIS UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-12-31
Last registration	2024-01-08
Complete history	See info



Registration #1	2014-12-31	11 mi
Registration #2	2017-10-07	35.413 mi
Registration #3	2018-09-21	52.020 mi
Registration #4	2019-10-05	67.589 mi
Registration #5	2020-12-29	77.016 mi
Registration #6	2020-12-31	77.016 mi
Registration #7		91,777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10,100 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number D4FDDU349475