





report date: 2024-03-29

General information

Make	FIAT
Model	500 L MULTIJET LOUNGE DUALOGIC
Colour	Grey
Year of manufacture	2014
Top speed	102 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2021-09-16

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date 2021-09-16

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2025-03-06
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	24
Total items failed	7

MOT #12		2024-03-04 11:03
MOT test i	number	334986709575
Result		✓ Passed
Next expi	y date	2025-03-06
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside rear lamp lens cracked and lamp full of water - advise replacement	ent
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or co	ords (5.2.3 (d) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weak	kened (1.1.14 (a) (ii))
Advice	Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn to 2.5m	nm (5.2.3 (e))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11 2024-03-04 11:03 **MOT** test number 477191711024 Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn to 2.5mm (5.2.3 (e)) Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Offside rear lamp lens cracked and lamp full of water - advise replacement **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2023-03-07 16:54
MOT test number	358371968741
Result	✓ Passed
MOT #9	2023-03-06 15:59
MOT test number	168322271578
Result	× Failed
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #8	2022-02-21 15:31
MOT test number	964824402429
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7 2021-03-04 13:24

MOT test number 620549739791

MOT #6 2021-02-17 09:25

MOT test number 688467053614

Result X Failed

Fail Nearside Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Advice Nearside Rear tyre has a nail in it

MOT #5 2020-02-17 16:29

MOT test number 200809371925

Result \rightarrow Passed

MOT #4 2020-02-12 16:59

MOT test number 816374293326

Result X Failed

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2019-11-16 18:05

MOT test number 898166212759

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing close to legal limit on inner and outer edges (5.2.3 (e))

Advice Front Brake disc worn, but not excessively Both O/S and N/S (1.1.14 (a) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-29

✓ Passed

MOT #2

MOT test number

669455873467

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2017-08-22 13:01

MOT test number 669705462131

Advice

Result

Nearside Front Tyre worn close to the legal limit Bold On Very Outer Edge (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Ow		الحالما	
C)W	ner	nısı	orv

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-30
Last registration	2024-03-04
Complete history	See info



Registration #1	2014-09-30	29 mi
Registration #2	2017-08-22	9.359 mi
Registration #3	2018-09-10	18.531 mi
Registration #4	2019-11-16	39.877 mi
Registration #5	2020-02-12	41.344 mi
Registration #6	2020-02-17	41.344 mi
Registration #7	2021-02-17	76.901 mi
Registration #8	2021-03-04	76.908 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91,777 esi
Registration #14		11.777 es
Registration #15		70.777 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Kerb weight	1320 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

5491039