



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-12-18
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-08
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	29
Total items failed	4

MOT #15	2023-06-09 11:20
MOT test number	218411539240
Result	✓ Passed
Next expiry date	2024-06-08

MOT #14	2022-01-25 12:26
MOT test number	289898429568
Result	✓ Passed

MOT #13	2019-11-11 17:14
MOT test number	768793500773
Result	✓ Passed
Advice	Parking brake lever has little reserve travel
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #12** 2019-11-11 12:04**MOT test number** 828283943469**Result** ✗ Failed

- MAJOR** Windscreen washer not working (3.5 (a))
- MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Parking brake lever has little reserve travel
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #11 2018-11-09 11:47**MOT test number** 209083222501**Result** ✓ Passed

- Advice** Rear silencer baffles loose inside
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #10 2017-11-03 16:11**MOT test number** 339092974835**Result** ✓ Passed

- Advice** Splash shields fitted
- Advice** Nearside Front headlamp lens deteriorated

**MOT #9** 2017-11-03 12:38**MOT test number** 783946871339**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Splash shields fitted**Advice** Nearside Front headlamp lens deteriorated**MOT #8** 2016-10-24 14:26**MOT test number** 992799208281**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit outer edge worn (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit outer edge worn (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2015-11-05 11:20**MOT test number** 246464534017**Result** ✓ Passed**MOT #6** 2015-11-04 14:33**MOT test number** 808619642464**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #5** 2014-10-30 12:14**MOT test number** 955693504347**Result** ✓ Passed**Notice** Both rear shock absorbers top shrouds detached**MOT #4** 2014-10-30 12:14**MOT test number** 658333304388**Result** ✗ Failed**Notice** Both rear shock absorbers top shrouds detached**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2013-10-21 11:27**MOT test number** 615144393211**Result** ✓ Passed**Notice** Windscreen damage to nearside caused by worn wipers also stone damage outside of line of vision**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-10-26 14:58**MOT test number** 178250702352**Result** ✓ Passed**MOT #1** 2012-10-26 11:48**MOT test number** 545830102394**Result** ✗ Failed**Fail** Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AV59VWF
Plate since	2019-06-29
Current registration	 AV59VWF
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-07
Last registration	2023-06-09
Complete history	See info



Registration #1	2009-11-07	23 mi
Registration #2	2012-10-26	14.606 mi
Registration #3	2012-10-26	14.606 mi
Registration #4	2013-10-21	20.016 mi
Registration #5	2014-10-30	26.440 mi
Registration #6	2015-11-04	32.850 mi
Registration #7	2015-11-05	32.851 mi
Registration #8	2016-10-24	40.130 mi
Registration #9	2016-10-24	40.130 mi
Registration #10	2016-10-24	40.130 mi
Registration #11	2016-10-24	40.130 mi
Registration #12	2016-10-24	40.130 mi
Registration #13	2016-10-24	40.130 mi
Registration #14	2016-10-24	40.130 mi
Registration #15	2016-10-24	40.130 mi
Registration #16	2016-10-24	40.130 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629