



report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SPORT
Colour	Maroon
Year of manufacture	-
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

<b>MOT #15</b>	2020-02-17 15:10
<b>MOT test number</b>	567678294440
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-02-18
<b>Advice</b>	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

<b>MOT #14</b>	2020-02-14 12:09
<b>MOT test number</b>	680319700413
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>DANGEROUS</b>	Offside Rear Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
<b>Advice</b>	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
<b>DANGEROUS</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

<b>MOT #13</b>	2019-02-19 14:39
<b>MOT test number</b>	429050712909
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge Both front tyre's are thin on inner edge (recommend tracking) (5.2.3 (e))



## MOT #12

2019-02-08 10:26

## MOT test number

545809078398

## Result

✗ Failed

**MAJOR** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Outer sill at the rear (6.1.1 (c) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge Both front tyre's are thin on inner edge (recommend tracking) (5.2.3 (e))

**MAJOR** Brake pipe excessively corroded Rear pipe running up over the sub frame (1.1.11 (c))

**MAJOR** Nearside Rear Anti-roll bar linkage pin or bush excessively worn Link bar (D Bush) (5.3.4 (a) (i))

**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

**MAJOR** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Outer sill at the rear (6.1.1 (c) (i))

**MAJOR** Brake pipe excessively corroded From the centre next to the fuel pipe (1.1.11 (c))

**MAJOR** Brake pipe excessively corroded Rear pipe running up over the sub frame (1.1.11 (c))

**MAJOR** Offside Rear Anti-roll bar linkage pin or bush excessively worn Link bar (D Bush) (5.3.4 (a) (i))

**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

## MOT #11

2018-02-10 11:47

## MOT test number

433216425705

## Result

✓ Passed

## MOT #10

2017-03-01 16:04

## MOT test number

767527361666

## Result

✓ Passed

**Advice** Oil leak

**Advice** Engine covers and under trays fitted

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Stop lamp has light sources not illuminating, but not more than 50% hi level (1.2.1b)

**Advice** Wipers smearing

**MOT #9** 2017-02-20 16:59**MOT test number** 168470400211**Result** ✗ Failed**Advice** Engine covers and under trays fitted**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Wipers smearing**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Oil leak**Advice** Stop lamp has light sources not illuminating, but not more than 50% hi level (1.2.1b)**MOT #8** 2016-03-04 14:40**MOT test number** 136524428359**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #7** 2015-02-20 17:33**MOT test number** 308381155057**Result** ✓ Passed

**MOT #6** 2015-02-18 11:04**MOT test number** 746409945017**Result** ✗ Failed

- Fail** Front registration plate deteriorated (6.3.1d)
- Fail** Offside Front Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)
- Fail** Offside Front Headlamp aim too low (1.8)

**MOT #5** 2014-03-08 09:50**MOT test number** 727187164009**Result** ✓ Passed

- Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Offside front track rod has slight play

**MOT #4** 2013-03-09 09:17**MOT test number** 156118263425**Result** ✓ Passed

- Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #3** 2012-02-21 09:42**MOT test number** 625402552089**Result** ✓ Passed

- Advice** Offside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Notice** Play in steering rack inner joint(s)

**MOT #2** 2011-03-05 10:29**MOT test number** 549834861042**Result** ✓ Passed



MOT #1	2010-03-12 13:41
MOT test number	150341270056
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>DE56VZM</b>
Plate since	2019-09-28
Current registration	<b>DE56VZM</b>
Plate since	2019-09-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-12-29
Last registration	2020-02-17
Complete history	<a href="#">See info</a>



Registration #1	2006-12-29	17 mi
Registration #2	2010-03-12	32.993 mi
Registration #3	2011-03-05	42.490 mi
Registration #4	2012-02-21	51.480 mi
Registration #5	2013-03-09	61.342 mi
Registration #6	2014-03-08	71.534 mi
Registration #7	2015-02-18	80.825 mi
Registration #8	2015-02-20	80.825 mi
Registration #9	2016-03-04	92.291 mi
Registration #10	2016-03-04	92.291 mi
Registration #11	2016-03-04	92.291 mi
Registration #12	2016-03-04	92.291 mi
Registration #13	2016-03-04	92.291 mi
Registration #14	2016-03-04	92.291 mi
Registration #15	2016-03-04	92.291 mi
Registration #16	2016-03-04	92.291 mi
Registration #17	2016-03-04	92.291 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1575 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	060628114505BG