





report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC TDCI
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1


Date 2021-09-12

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-07-19
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	45
Total items failed	8

MOT #20	2023-07-04 11:04
MOT test number	162242852390
Result	✓ Passed
Next expiry date	2024-07-19

MOT #19		2022-07-05 11:23
MOT test	number	321307260484
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm(195/55R16) (5.2.3 (e))
Advice	Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))	
Advice	Rear,tyres,worn,on,outer,edge	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #18 2022-07-05 11:23

MOT test number 367088103772

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm(195/55R16) (5.2.3 (e))

Advice Rear, tyres, worn, on, outer, edge

Pass with rectification Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #17 2021-07-19 11:14

MOT test number 579594496747

Result Passed

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #16 2021-07-19 11:14

MOT test number 398204128850

Result × Failed

Pass with rectification

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps

(4.7.1 (b) (ij))

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #15 2020-06-24 13:21

MOT test number 155161044265

Result \(\sqrt{Passed} \)

Advice Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #14 2020-06-24 10:19

MOT test number 976139319963

Result X Failed

Fail Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #13 2019-07-03 08:41

MOT test number 171039391301

Result

Passed

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #12 2018-07-20 09:44

MOT test number 465838644666

Result

Passed

MOT #11 2018-07-18 08:26

MOT test number 538494375280

Result X Failed

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #10		2017-08-22 14:21
MOT test	number	440652524642
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Both front lower arms - both ball joint gaitors - badly perished	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear exhaust box corroded - no leaks	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Engine roll restrictor split	

MOT #9		2016-08-15 08:26
MOT test	number	892611276585
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Additional brake lamp not working	
Advice	Nearside Front Tyre worn close to the legal limit Outer edge worn (4.1.E.1)	
Advice	Wipers poor	

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT #8 2016-08-15 08:26 184958855027 **MOT** test number Result × Failed **Advice** Additional brake lamp not working Advice Front Brake pad(s) wearing thin (3.5.1g) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Wipers poor Pass with rectification Offside Stop lamp not working (1.2.1b) **Advice** Nearside Front Tyre worn close to the legal limit Outer edge worn (4.1.E.1)

MOT #7

MOT test number

Result

Advice Headlamp adjuster altered

2015-08-17 00:00

313692545295

Passed

MOT test number

638002034240

Result

Notice Nail in nearside rear tyre


Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Vehicle's internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 7/16



report date: 2024-03-28



MOT #4		2013-08-30 14:15
MOT test	number	208132643256
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	High level brake light inop	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in nearside rear tyre	

MOT #3	2012-08-31 16:33
MOT test number	348664342482
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2		2012-08-31 16:33
MOT test number		967844642297
Result		X Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Advice Nearside Rear T	yre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #1 2012-02-20 11:48
MOT test number 189021652077

CarCheck.co.uk page 9/16



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

^	
Owner	hictory
OWILL	IIISCUIV

e when mistery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-24
Last registration	2023-07-04
Complete history	See info



Registration #1	2009-03-24	21 mi
Registration #2	2012-02-20	24.920 mi
Registration #3	2012-08-31	25.953 mi
Registration #4	2013-08-30	31.585 mi
Registration #5	2014-08-20	36.424 mi
Registration #6	2015-08-17	41.389 mi
Registration #7	2016-08-15	46.592 mi
Registration #8	2016-08-15	46.592 mi
Registration #9	2017-08-22	51.330 mi
Registration #10	2018-07-18	55.145 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 16/1