





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 CRDI SE BLUE DRIVE
Colour	Blue
Year of manufacture	2016
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	260 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-08-23

Pictures 24

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date	2021-07-23	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/11



SD66VZL report date: 2024-03-29

MOT history

MOT expiry date	2024-09-07
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #6		2023-09-08 09:37
MOT test	number	541018404393
Result		✓ Passed
Next expi	ry date	2024-09-07
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weak	rened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))

MOT #5	2023-09-08 08:20
MOT test number	157583629756
Result	X Failed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4		2022-08-23 13:07
MOT test	number	186389795624
Result		✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2021-07-28 14:08
MOT test number	296987703269
Result	✓ Passed
MOT #2	2020-08-28 14:45
MOT test number	256461598653
Result	✓ Passed
MOT #1	2019-12-02 10:49
MOT test number	136926721706
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		PΑΙ
PROPERTY.		

	More info >	
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	OK SIE	
Plate since		
Current registration	NK SIN	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



SD66VZL report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-12-30
Last registration	2023-09-08
Complete history	See info



Registration #1	2016-12-30	7 mi
Registration #2	2019-12-02	20.692 mi
Registration #3	2020-08-28	24.235 mi
Registration #4		11.777 es
Registration #5	2021-07-28	30.086 mi
Registration #6		111,1117 aug
Registration #6 Registration #7		11.777 es
		11.777 es

More info >

CarCheck.co.uk page 10/11



SD66VZL report date: 2024-03-29

Car features

S0225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4120 mm
Wheel base	2615 mm
Kerb weight	1380 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number D4FBGZ097375