





report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER SD ALL4
Colour	White
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 3

Date 2024-02-04

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-07-17

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-16

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



YP12WTE report date: 2024-03-28

MOT history

MOT expiry date	2024-10-24
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #11	2023-10-25 11:47
MOT test number	901017983600
Result	✓ Passed
Next expiry date	2024-10-24

MOT #10		2022-09-13 10:02
MOT test i	number	470753521468
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2021-08-04 13:06
MOT test number	216406035034
Result	✓ Passed

MOT #8	2021-02-19 09:39
MOT test number	727276664438
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2021-02-17 08:22

MOT test number 664641894673

Result X Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2020-02-17 15:32

MOT test number 501447547153

Result

Passed

Advice Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Driver's view Items removed from driver's view prior to test multiple items removed from dash and spedo (3.1 (a) (ii))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-03-06 11:16

MOT test number 313009669876

Result

Passed

Advice Items removed from driver's view prior to test

Advice Under trays fitted

Minor Central Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Engine covers fitted

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2018-02-07 14:14

MOT test number 197281666796

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear tyre cracks in tread

Advice Items removed from driver's view prior to test

Advice Nearside Rear tyre cracks in tread

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #3 2017-03-01 12:19

MOT test number 872377654210

Advice Items removed from driver's view prior to test

Advice Front wipers smearing

MOT #2 2016-03-09 09:47

MOT test number 983636025691

Result
✓ Passed

MOT #1 2015-05-06 14:41

MOT test number 255916525413

Result

Passed

Notice Both front tyre edges balding

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



YP12WTE report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

manage of the same	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NAME OF THE PROPERTY OF THE
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.5	

Contact info

More info >

CarCheck.co.uk page 10/12



YP12WTE report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-31
Last registration	2023-10-25
Complete history	See info



Registration #1	2012-05-31	28 mi
Registration #2	2015-05-06	39.782 mi
Registration #3	2016-03-09	48.841 mi
Registration #4	2017-03-01	53.390 mi
Registration #5	2018-02-07	57.202 mi
Registration #6	2019-03-06	61.162 mi
Registration #7	2020-02-17	64.655 mi
Registration #8	2021-02-17	66.326 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1395 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12

Number of axles 2

Engine number 72408315