





General information

Make	MERCEDES-BENZ
Model	CLS CLS220 BLUETEC AMG LINE
Colour	Silver
Year of manufacture	2015
Top speed	138 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history			
Entry 1			
Date	2021-09-1	5	
Pictures	5		
Listing price	View repor	<u>t</u>	
	We are HIGHLY RATED Customer reviewed on Customer reviewed on Customer reviewed on Customer deviewed on Customer d	We hpi check our cars	Video viewing with one of our team. Book a video viewing with one of our team. Coldeo viewing with one of our team. Coldeo viewing with one of our team.

source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	24
Total items failed	5

MOT #8		2023-11-08 11:18
MOT test	number	100845542317
Result		Passed
Next expiry date 2024-11-08		2024-11-08
Advice (e))	Offside Front Tyre worn close to legal limit/worn on edge outer tread edges bal	d / perished (5.2.3
Advice	Nearside Front Tyre slightly damaged/cracking or perishing edges (5.2.3 (d) (ii))

MOT #7	2023-11-03 12:05
MOT test number	361902992713
Result	🗙 Failed
Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))	
Advice Offside Front Tyre worn close to legal limit/worn on edge outer tread edges (e))	bald / perished (5.2.3
Advice Offside Rear Tyre worn close to legal limit/worn on edge inner tread edges	(5.2.3 (e))
Fail Offside Rear Parking (secondary brake) on a single line braking system has ina wheel (1.3.1 (a) (i))	dequate effort at a
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing edges (5.2.3 (d)) (ii))





MOT #6	2022-11-09 10:33	3
MOT test	number 12194718574	7
Result	✓ Passed	k
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge Wearing inside edge (5.2.3 (e))	

MOT #5	2021-11-02 11:05
MOT test number	908015826250
Result	✓ Passed

MOT #4		2020-11-09 12:52
MOT test	number	438158095548
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on limit 1.6 mm (5.2.3	(e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing outer side wall (5.2.	.3 (d) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	



MOT #3		2020-11-04 14:26
MOT test	number	525225860371
Result		🗙 Failed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Er	ngine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on limit 1.6 mm (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing outer side wall (5.2.3	3 (d) (ii))

MOT #2	2019-11-05 08:47
MOT test number	272262086322
Result	✓ Passed

MOT #1	2018-06-12 12:52
MOT test number	696762727880
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

SC15KKV

report date: 2024-03-28



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 8 November 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L'ERNPE
Туре	
Damage 2	AMPLE
	E Store
Date	L.
Category	AMPL
Туре	

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Carrent registration Plate since	





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report here and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-06-30
Last registration	2023-11-08
Complete history	See info



Registration #1	2015-06-30	6 mi
Registration #2	2018-06-12	37.757 mi
Registration #3	2019-11-05	47.781 mi
Registration #4	2020-11-04	54.750 mi
Registration #5	2020-11-09	54.812 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.000 est

More info >





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2075 mm
Height	1418 mm
Length	4937 mm
Wheel base	2874 mm
Kerb weight	1790 kg
Max. allowed weight	2275 kg
Additional information	
Fuel tank capacity	59
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	65192432556533