





report date: 2024-03-28

General information

Make	HONDA
Model	FR-V I-CTDI EX
Colour	Silver
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-21

Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1


Date 2021-09-20

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-10-12
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	10
Total items failed	7

MOT #19	2023-10-13 15:08
MOT test number	786887406392
Result	✓ Passed
Next expiry date	2024-10-12

MOT #18	2023-10-06 14:01
MOT test number	453641435489
Result	X Failed
Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Advice Child Seat fitted not allowing full inspection of adult belt Nsr + Osr	
Advice Tyre slightly damaged/cracking or perishing Both rears (5.2.3 (d) (ii))	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Fail Battery insecure and likely to fall from carrier (4.13 (a) (ii))	

MOT #17	2022-10-05 14:11
MOT test number	963744807750
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin just legal (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #16	2021-10-08 14:39
1101 1120	2021 10 00 11:33

MOT test number 741922346268

MOT #15 2021-10-07 13:32

MOT test number 598867711396

Result X Failed

Fail Nearside Front Hydraulic brake calliper damaged Restriction in free movement of brake calliper front (1.1.16 (a) (i))

Fail Nearside Rear Axle has excessive vertical movement between stub axle and axle beam Stabiliser Mounting or Rear anti roll bar D bushes (5.1.2 (c) (i))

MOT #14 2020-08-28 08:58

MOT test number 440732326049

Result ✓ Passed

MOT #13 2019-08-29 09:44

MOT test number 497750700164

Result
✓ Passed

MOT #12 2018-09-14 09:34

MOT test number 864824687920

Result

Passed

MOT #11 2017-09-18 11:54

MOT test number 858985800629

Advice Offside Rear Tyre worn close to the legal limit inneredge (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit inneredge (4.1.E.1)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10		2017-09-18 11:54
MOT test number		862701237136
Result		× Failed
Pass with rectification	Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Offside Rear Tyre worn close to the legal limit inneredge (4.1.E.1)		
Advice Nearside Front Tyre worn close to the legal limit inneredge (4.1.E.1)		

MOT #9	2016-09-12 11:44
MOT test number	652431509296
Result	✓ Passed
MOT #8	2015-09-14 08:43
MOT test number	611312296090
Result	✓ Passed
Advice Four child seats fitted	

MOT #7	2014-09-05 09:58
MOT test number	307058644494
Result	✓ Passed
MOT #6	2013-08-30 15:14
MOT test number	398322643280
Result	✓ Passed
MOT #5	2012-09-18 11:49
MOT test number	646362962266
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4 2012-09-18 11:49

MOT test number 575522862217

Result X Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

MOT #3 2011-09-06 15:53

MOT test number 117949041253

Result ✓ Passed

MOT #2 2011-09-05 11:44

MOT test number 817388741289

Result X Failed

Fail Offside Front Side repeater not working (1.4.A.2c)

MOT #1 2010-09-18 11:13

MOT test number 924271660261

Result
✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



RO57XSV report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	OK SIE
Flate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-18
Last registration	2023-10-13
Complete history	See info



Registration #1	2007-09-18	20 mi
Registration #2	2010-09-18	30.412 mi
Registration #3	2011-09-05	38.308 mi
Registration #4	2011-09-06	38.317 mi
Registration #5	2012-09-18	47.818 mi
Registration #6	2013-08-30	56.185 mi
Registration #7	2014-09-05	63.553 mi
Registration #8	2015-09-14	70.257 mi
Registration #9	2016-09-12	77.086 mi
Registration #10	2017-09-18	85.030 mi
Registration #11	2017-09-18	85.030 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	N22A12502504

CarCheck.co.uk page 13/13